FD

9-NORMAL, NB, 100439, SB141 4802

220250224 **4452**

U W AZ ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

Ford.com	ICLE DESCRIPTION F-150 2025 F-150 4X4 SUPERCF 145" WHEELBASE 3.5L POWERBOOST FULL HYBRID ELEC 10-SPD AUT	C HYBRID INTI	SF A	70516	EPA DOT Fuel Economy and En Fuel Economy R 2 2 MPG Standard P 84 MPG. T MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR	INCERTRACTIONAL INTERIOR • 10-WAY PWR DRV & MULTI-ADJ PWR FRT PASS • 12" PRODUCTIVITY SCREEN • A/C W/DUAL CLIMATE CONTROL • ADAPTIVE CRUISE CONTROL • AUTO DIM REARVIEW MIRROR • HTD PREM WRAPPED STR WHL • HTD/VENTILATED FRT SEATS • PWR DRIVER/PASS LUMBAR • PWR DRIVER/PASS LUMBAR • REMOTE START SYS • REVERSE BRAKE AS • REVERSE BRAKE AS • REVERSE SENSING A • SIRIUSXM® W360L- • SYNC®4 W/EVR & 12 (MSRP) 2,670.00 1,900.00 NO CHARGE NO CHARGE 850.00 555.00 275.00		FFIC ALERT • AIRBAGS - FRONT SEAT ECT 5GWI-FI MOUNTED SIDE IMPACT ICS MODEM • AIRBAGS - SAFETY CANOPY® SS W/PUSH • CTR HIGH MOUNT STOP LAMP TEM • SECURE PKG 1 YR INCLUDED SIST W/AEB • STEM SIST MAEB • TIRE PRESSURE MONIT SYS SIST MAEB • STEM SIST MARD • 3YR/36,000 BUMPER / BUMPER • NA AK&HI • SYR/60,000 ROADSIDE ASSIST		Image: A grade in the compared to other vehicles of similar size Image: A grade in the compared to other vehicles of similar size
FX4 OFF-ROAD PACKAGE .SKID PLATES .LINER-TRAY STYLE-NO CARPET MA STANDARD FUEL TANK BED UTILITY PACKAGE .PRO ACCESS TAILGATE WHEEL WELL LINER	1,095.00 1,620.00 180.00				Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★), w Source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327-
	This label is affixed pursu Information Disclosure Ac	RAIL TEM #: 71-705Z O/T 2 ant to the Federal Automobile t. Gasoline, License, and Title Fees, not included. Dealer installed	Ford vehicle, you'll fi		IFTFW5LD3SFA70516 WARNING: Operating, servicing and maintaining a par- vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause cand To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen



2202502244452