FD

9-NORMAL, NB, 101796, SF171 6007

220250626 **3925**

ford.com STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE		ICONIC SILVER METALLIC INTERIOR			EPA DOT Fuel Economy and Er Fuel Economy MPG Standard Standard 87 MPG. MPG
EXTERIOR • BUMPERS- BODY COLOR • LED FOG LAMPS • LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS • LED SIDE-MIRROR SPOTLIGHTS • LED TAIL LAMPS • POWER MIRRORS • POWER MIRRORS • POWER SLIDING REAR WINDOW W/DEFROST & PRIVACY TINT • REMOTE TAILGATE RELEASE • RUNNING BOARD-PWR DEPLOY INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 701A • PLATINUM SERIES OPTIONAL EQUIPMENT/OTHER .20" PAINTED GLOSS EBONY BLACK .275/60R20 BSW ALL-TERRAIN 3.55 ELECTRONIC LOCK RR AXLE 7100# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS BLUECRUISE EQUIP: 1 YEAR PLAN FX4 OFF-ROAD PACKAGE .SKID PLATES .FLOOR LINER - TRAY STYLE EXTENDED RANGE 36GAL FUEL TANK DEALER INSTALLED OPTIONS SecuriCodeÖ Wireless Keyless E	Internet of the second	EUNCTIONAL 9 360-DEGREE CAMEI 9 BED UTILITY PKG 9 BLIS W/CROSS TRA 9 FORDPASS™ CONN HOTSPOT TELEMAT 1 INTELL ACCESS W/I 9 POST-COLLISION BI 9 REVERSE BRAKE AS 9 REVERSE SENSING REAR VIEW CAMER/ 9 SYNC®4 W/EVR & 1 1 TOW/HAUL PKG	A ADVANG AIRBAG AIRBAG FFIC ALERT MOUNT ECT 5GWI-FI CS MODEM USH START TEM AND AKING SIST AND AND AND SIST AND AND SIST AND AND SIST AND AND SIST AND AND SIST SIST AND SIST SIST AND SIST SIST AND SIST	000 BUMPER / BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST 0,000 HYBRID BATTERY (MSRP) \$74,905.00 1,545.00	indication 16 24 highway 3.3 gallons per 100 miles indication 5.3 gallons per 100 miles indication indication 10 indication indication
	RAMP ONE CH12 RAMP TWO	CONVOY /#: 24-B39Q O/T 2	TOTAL MSRP Scan The QR Co get more details this vehicle		IFTFW7L8XSFB58865 WARNING: Operating, servicing and maintaining a paye vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause car
	State and Local taxes are not	Gasoline, License, and Title Fees,	SF171 N RB 2X 565	001796 06 17 25	lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer

2202506263925

