KAN-003250 _{MD}	9-NORMAL,NB,203250,RD152 110	048 220240422 5457 BLEND 5457	ULC U W MD CERT CERT CERT TRD RAMP BUMP (CAMP BOOK EXFL ROTA	
VEHIC	LE DESCRIPTION -150 2024 F-150 4X4 SUPER CAB 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO TRANS	EXTERIOR OXFORD WHINTERIOR DARK SLATI DARK SLATI AMVFM STEREO BLIS W/CROSS-TRAFFIC ALERT CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECTOR CURVE CONTROL FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST LANE-KEEPING SYSTEM POST-COLLISION BRAKING PRE-COLLISION ASSIST W/AEB REVERSE SENSING AND REAR VIEW CAMERA SELECTSHIFT® SYNC®4 W/EVR & 12" SCREEN PRICE INE BASE PRIC TOTAL OPT	RK D80230 RIOR FORD WHITE ROR RK SLATE VINYL 40/20/40 SIGR FIC ALERT CH ALERT CH SGWI-FI NNECTOR CT 5GWI-FI SMODEM EM KING ST W/AEB ND ST W/AEB ND	EXAMP BOOK EXFL ROTA FUEL ECONOMY FUEL ECO	Standard Pickup Trucks 73 MPG. The best vehic MPGe. way conomy & Greenho 4 de emits 472 grams CO2 pe g fuel also create emission d riving conditions and costs \$9,750 to fuel ove MPGe is miles per gaso and smog. vehicles AFETY RATINO AFETY RATINO AFETY RATINO AFETY RATINO
	RAMP ONE CU2G RAMP TWO	CONVOY 27-B883 O/T 2 Ford Cred	L MSRP \$48,545.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of sir Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover Based on the risk of rollover in a single-vehicle craster Star ratings range from 1 to 5 stars (*** Source: National Highway Traffic Safetron www.safercar.gov or 1-8 1FTFX1L51RKD8	$ \begin{array}{c} \star & \star & \star & \star \\ \star & \star & \star & \star \\ \star & \star &$
This label is affixed pursuant Information Disclosure Act. State and Local taxes are not options or accessories are n		line, License, and Title Fees, uded. Dealer installed RD152 N	N RB 2X 440 003250 04 15 24	To minimize exposure, avoid breathing exhaust, do investigation of the vehicle in a well-ventilated area and wear gloves or For more information go to www.P65Warnings.ca.go	not idle the engine exce wash your hands freque

2202404225457

