ULC U W C

KTP-001537 AZ	9-NORMAL,NB,201537,RA262 79	32	CERT CERT CERT TRD RAMP BUMP	CAMPBOOKEXFLROTA 1375/1
VEH CONTROLOGIONAL CONTROL C	ICLE DESCRIPTION SUPPERDIX SUPPERDIX Supperdix Not the state of the	EXTERIOR OXFORD WHI INTERIOR MEDIUM DAR • 4-WHEEL ANTILOCK BRAKE SYS • FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM • HILL START ASSIST • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SYNC®4 W/8" SCREEN • TWIN I-BEAM INDEPENDENT FRT SUSPENSION W/STAB BAR	RE DO9324 TE TS STATE CLOTH STATE CLOTH DAVANCETRAC™ WITH RSC® AIRBAGS - SAFETY CANOPY® BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGS BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGS BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGS SECURILOCK® ANTI-THEFT SYS BORT-CRASH ALERT SYS™ MENTION	CAMP BOOK EXFL ROTA California Air Resources Board Environment These ratings are not directly comparable to For information on how to compar Protect the environment. Cho Greenhouse Gas Rating (tailpipe only A+ Cleaner Using alternative for Vehicle emissions are a primary contributor to climat California Air Resources Board based on this vehicle?
CAMPER PACKAGE JACK UPFITTER SWITCHES 190AMP(GAS)/250AMP(6.7L) ALTR CLOTH 40/20/40 SEAT	160.00 165.00 NO CHARGE 100.00 100	CONVOY 71-F281 O/T 5B the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed BA262 N	MSRP \$48,755.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right or you. See your dealer for details or visit www.ford.com/finance.	IFTRF3AA4RED09324 Image: Servicing and maintaining a passen Vehicle can expose you to chemicals including engine exha Iead, which are known to the State of California to cause cancer at To minimize exposure, avoid breathing exhaust, do not idle the envehicle in a well-ventilated area and wear gloves or wash your har For more information go to www.P65Warnings.ca.gov/passenger-vence

05/02/2024

