
KAN-006138 _{TX}	9-NORMAL,NB,106138,RC131 27	120240321 5458	ULC U W CERT CERT TRD RAMP	CAMP BOOK EXFL ROTA	02 607/
	CLE DESCRIPTION TRANSIT 2024 150 LR CARGO RWD	EXTERIOR	^{RK} A54795	California Air Resou	rces Board
ford.com	130" WHEELBASE 3.5L PFDI V6 (GAS) 10-SPEED TRANSMISSION	OXFORD WHI INTERIOR	TE ZO GRAY VINYL	Enviro	onmen
STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE				These ratings are not direc For information o	· ·
EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING	INTERIOR • AIR CONDITIONING • ASSIST HANDLE - B-PILLAR • ASSIST HANDLES - A-PILLAR • CENTER CONSOLE • INTERIOR LIGHTING - LED • LOCKING GLOVE BOX • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER	EUNCTIONAL AUTO HIGH-BEAM HEADLAMPS ELECTRONIC PWR ASST STEER FORWARD COLLISION WARNING HILL START ASSIST LANE-KEEPING SYSTEM POST-COLLISION BRAKING PRE-COLLISION ASSIST W/AEB REAR VIEW CAMERA W/ TRAILER HITCH ASSIST SELECTABLE DRIVE MODES SIDE-WIND STABILIZATION	SAFETY/SECURITY • 3 POINT SAFETY BELTS • ADVANCETRAC™ WITH RSC® • AIRBAGS ⊠ FRONT, SIDE AND SAFETY CANOPY® SYSTEM • BRAKES - 4WHEEL DISC W/ABS • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS™ • TIRE PRESSURE MONIT SYS WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 ROADSIDE ASSIST	Protect the environ Greenhouse Gas Rat A+ Cleaner	onment. Ch ing (tailpipe onl C
				Vehicle emissions are a primary co California Air Resources Board bas	
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.101A 3.73 NON-LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET 800# GVWR PACKAGE 50 STATE EMISSIONS E-85 FLEX FUEL CAPABLE	(MSRP) NO CHARGE NO CHARGE NO CHARGE NO CHARGE		\$46,890.00	GOVERNMENT 5-ST Overall Vehicle Score Based on the combined ratings of frontal Should ONLY be compared to other vehicle Frontal Driver Crash Passenger Based on the risk of injury in a frontal importance Side Front seat Crash Rear seat Based on the risk of injury in a side impared Side Front seat Crash Rear seat Based on the risk of injury in a side impared Star ratings range from 1 to 5 stars Source: National Highway Traff www.safercar.go	Not Rate , side and rollover. cles of similar size and
	CHTB	ΤΟΤΑΙ	. MSRP \$48,985.00		86RKA54795
	RAMP TWO	52-F067 O/T 5C Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing an vehicle can expose you to chemical lead, which are known to the State of Califor To minimize exposure, avoid breathing exh	d maintaining a passe s including engine exh ornia to cause cancer paust, do not idle the e
	Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	asoline, License, and Title Fees, ncluded. Dealer installed RC131 N	SPECIAL ORDER RB 2X 435 006138 03 13 24	vehicle in a well-ventilated area and wear of For more information go to www.P65Warni	gloves or wash your hange une e ngs.ca.gov/passenger

1202403215458



engine except as necessary, service your hands frequently when servicing your vehicle. ger-vehicle

www.ford.com/help/privacy-terms/

for help