Go Further ford.com	DESCRIPTION RONCO SP 2022 BIG BEND 4X4 5-PASSENGER 1.5L ECOBOOST ENGINE 8-SPD AUTO TRANSMISSION	EXTER SH/ INTER	IOR ADOW BLACK	35092 '	EPA DOT Fuel Economy and E Fuel Economy P 26 MPG Small SU The best
ACTIVE GRILLE SHUTTERS     DOOR HANDLES - BLACK     EASY FUEL® CAPLESS FILLER     GRL-GRAY-"BRONCO" WHT     HEADLAMPS - AUTO HIGH BEAM     HEADLAMPS - AUTO HIGH BEAM     HEADLAMPS - LED     LIFTGATE W/ LIFTGLASS     MIRRORS - HTD/POWER GLASS     PRV GLS-2ND RW/LIFTGATE     REAR INT WIPER/WASH/DFRST     ROOF-RACK SIDE RAILS-BLACK     TAILLAMPS-LED     WHEEL LIP MOLDINGS - BLACK  INCLUDED ON THIS VEHICLE  OPTIONAL EQUIPMENT/OTHER .EQUIPMENT GROUP 200A .17" CARBON GRAY HIGH GLS WHL 225/65 R17 102H A/S BSW TIRES     S0 STATE EMISSIONS	EXTRA CHARGE INTERIOR  • 1-TOUCH DOWN DRIVER WINDOW • 60/40 SPLIT FOLD REAR SEAT • DUAL ILLUM VIS VANITY MIRR • EASY CLEAN CLOTH BUCKETS • ELECTRONIC AUTO TEMP CTRL • FLOOD LIGHT ADJ LIFTGATE • ILLUMINATED ENTRY SYSTEM • MANUAL PASS SEAT - 4-WAY • MOLLE STRAP SYSTEM • POWERPOINTS - 12V • RUBBERIZED CARGO FLOOR • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • USB A AND C • O CHARGE • O CHARGE		CH AIRBAG - DRIV C/ABS AIRBAGS - DL AIRBAGS - DL AIRBAGS - DL AIRBAGS - SA T 4GWI-FI FRT-PASS SEL MODEM INDIV TIRE PR SH START LATCH CHILD //WASHER PERIMETER A SECURILOCKG TRY SIDE AIRBAGS AK&HI SOS POST-CF PLINK® IT SYS-5 WARRANTY 3YR/36,000 BL 5YR/60,000 PC	C <sup>™</sup> WITH RSC® VER KNEE JAL STAGE FRONT IFETY CANOPY® NSING SYSTEM EESS MONIT SYS SAFETY SYSTEM LARM ® ANTI-THEFT SYS BASH ALERT SYS™ JMPER / BUMPER DWERTRAIN DADSIDE ASSIST (MSRP) \$29,980.00	Image: Additional state of the state of
	RAMP ONE RH27 RAMP TWO	RAIL	Whether you decide Vehicle, you'll find th	<b>31,475.00</b> to lease or finance your e choices that are right	www.safercar.gov or 1-888-32 3FMCR9B60NRD35092
		e Federal Automobile line, License, and Title Fees, uded. Dealer installed	For you. See your dea www.ford.com/finar         NC311 N RB X 225 00446		vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/pass

