HRM-005421 _{TX}	9-NORMAL, NB, 105421, RC221 36	93	UTC U U		AMPBOOKEXFLROTA 00
VEHIC	CLE DESCRIPTION MAVERICK 2024 XL FWD 121" WHEELBASE 2.5L HYBRID ENGINE AUTO CV TRANSMISSION	EXTERIOR OXFORD INTERIOR BLACK • 4-WHEEL ANTILOCK BRAKE • 8.0" CTR STACK TOUCHSCR • AM/FM STEREO W/6 SPEAKE • APPLE CARPLAY™ AND ANDROID AUTO™ • BATTERY SAVER FEATURE • CRUISE CONTROL • ELECTRIC PARKING BRAKE • ELECTRIC PARKING BRAKE • FORDPASS™ CONNECT • PRE-COLLISION ASSIST W/A • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • REMOTE START- FORDPASS • REMOTE START- FORDPASS	CERTICERTICERTI TRD RA RR A8103 WHITE WHITE DNYX-MED DK SLATE TRI SYS EN SYS AIRBAGS - SAFETY CANC BELT-MINDER CHIME LATCH CHILD SAFETY SY SECURILOCK® ANTI-THE TIRE PRESSURE MONITS SYR/60,000 BUMPER / BL SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN SYR/100,000 HYBRID UNI -COMPONENTS IF EQUIPS	MP BUMP C 34 34 STEM FT SYS SYS	AMP BOOK EXFL ROTA 2962/ PAPE BOOK EXFL ROTA 2002/ PAPE POOK EXFL ROTA 2002/ PAP
		JGL			Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size an Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover * * * * Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (* * * * *), with Source: National Highway Traffic Safety Administs www.safercar.gov or 1-888-327-42
	RAMP ONE RA5B	то	TAL MSRP \$26,49	5.00	3FTTW8A32RRA81034
	RAMP TWO	52-R369 O/T 5B Ford 0	Whether you decide to lease or five vehicle, you'll find the choices th for you. See your dealer for detai www.ford.com/finance.	at are right	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ext lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	soline, License, and Title Fees, Icluded. Dealer installed	SPECIAL ORDER 221 N RB 2X 415 005421 03 22 2	4	To minimize exposure, avoid breathing exhaust, do not idle the evenicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

