HRM-005309 AZ	9-NORMAL, NB, 005309, SE272 <b>18</b>	819	CERTCERTCERT TRD RA	<b>o</b> Ampbumpcam	PBOOKEXFLROTABATT	0( 3367,
	121" WHEELBASE 2.0L ECOBOOST ENGINE IN AUTOMATIC TRANSMISSION		ATURE • BELT-MINDER CHIME   • BRAKE • LATCH CHILD SAFETY SYSTEM   ASST STEER • SECURILOCK® ANTI-THEFT SYS   IECT 5GWI-FI • TIRE PRESSURE MONIT SYS   ICS MODEM • SYR/36,000 BUMPER / BUMPER   SIST W/AEB • SYR/60,000 POWERTRAIN   • MODES • SYR/60,000 ROADSIDE ASSIST		fueleconomy.gov Calculate personalized estimates and compare vehicles	
		JGG			Frontal CrashDriver PassengeBased on the risk of injury in a frontal i Should ONLY be compared to other verSide CrashFront seat Rear seatBased on the risk of injury in a side im RolloverBased on the risk of rollover in a singleStar ratings range from 1 to 5 star Source: National Highway Tra- www.safercar.	impact. ehicles of similar size a $\star \star \star$ appact. e-vehicle crash. rs ( $\star \star \star \star$ ), wi
	CA4R	то	TAL MSRP \$32,4	95.00	3FTTW	/8BA1SRB02054
	RAMP TWO		n The QR Code to more details about		WARNING: Operating, servicing	and maintaining a pass
	TIEW#:		s vehicle		vehicle can expose you to chemic lead, which are known to the State of Ca	cals including engine ex
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not i	soline, License, and Title Fees, cluded. Dealer installed SE2	<b>SPECIAL ORDER</b> 272 N RB 2X 560 005309 05 2		To minimize exposure, avoid breathing e vehicle in a well-ventilated area and wea For more information go to www.P65Wa	exhaust, do not idle the

