HRM-006365 <sub>MD</sub>	9-NORMAL,NB,006365,RC151 83	97	CERT CERT CERT TR	O D RAMP BUMP C	AMP BOOK EXFL ROTA	00 3331/
	CLE DESCRIPTION MAVERICK 2024 XLT FWD 121" WHEELBASE 2.5L HYBRID ENGINE AUTO CV TRANSMISSION	INTERIOR	RD WHITE	712	Fuel Economy	DMY and Env MPG Small Pickup MPG. The be
EXTERIOR • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBED™ STORAGE SYSTEM • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS - LED AUTO HI-BEAM • HEADLAMPS-LED AUTO ON/OFF • POWER MIRRORS • POWER TAILGATE LOCK • WIPERS- INTERMITTENT	INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • CRUISE CONTROL • DUAL SLIDING SUNVISORS • MANUAL A/C, SINGLE ZONE • MAP POCKETS-PASSENGER • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL W/ SELECTABLE DRIVE MODES • UNIQUE CLOTH BUCKET SEATS • USB A AND C • VINYL SOFT CONSOLE LID	FUNCTIONAL • 8.0" CTR STACK TOUCHSC • AM/FM STEREO W/6 SPEA • APPLE CARPLAY™ AND ANDROID AUTO™ • BATTERY SAVER FEATURE • CARGO BOX TIE DOWN HC • ELECTRIC PARKING BRAK • ELECTRIC PARKING BRAK • ELECTRONIC PWR ASSTS • FADE-TO-OFF INTERIOR LI • FORDPASS™ CONNECT • PRE-COLLISION ASSIST W • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • REMOTE START- FORDPAS	KERS • BELT-MINDER CHIM • LATCH CHILD SAFE • PERIMETER ALARM • SECURILOCK® ANT • SECURILOCK® ANT • TIRE PRESSURE MO • TIRE PRESSURE MO • TIRE PRESSURE MO • TIRE PRESSURE MO • SYR/36,000 BUMPE • SYR/60,000 POWER • SYR/60,000 POWER • SYR/60,000 POWER • SYR/60,000 HYBRI • COMPONENTS IF E	ME ETY SYSTEM A TI-THEFT SYS ONIT SYS R / BUMPER ITRAIN IDE ASSIST ID UNIQUE	combined city/hwy c 2.7 gallons per 100 n Annual fuel COS \$1,450 \$1,450 Actual results will vary for many re- vehicle. The average new vehicle of based on 15,000 miles per year at \$ emissions are a significant cause of	Fuel Economy & D This vehicle emits 237 g distributing fuel also creater
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER 2.5L HYBRID ENGINE AUTO CV TRANSMISSION FLR LNRS W/CARPETED MATS FULL SIZE SPARE TIRE TRAILER HITCH RECEIVER BEDLINER - SPRAY-IN 50 STATE EMISSIONS FRONT LICENSE PLATE BRACKET	(MSRP) 1,500.00 NO CHARGE 175.00 115.00 100.00 495.00 NO CHARGE NO CHARGE	BAS TOT TOT	CE INFORMATION DE PRICE TAL OPTIONS/OTHER TAL VEHICLE & OPTIONS/OTHER TINATION & DELIVERY TINATION & DELIVERY	(MSRP) \$26,315.00 2,385.00 28,700.00 1,595.00	<b>fueleconom</b> Calculate personalized estimates <b>GOVERNMENT Overall Vehicle Score</b> Based on the combined ratings of   Should ONLY be compared to oth <b>Frontal</b> Driver <b>Crash</b> Passer   Based on the risk of injury in a fro   Should ONLY be compared to oth <b>Side</b> Front s <b>Crash</b> Rear set   Based on the risk of injury in a side <b>Side</b> Front s <b>Crash</b> Rear set   Based on the risk of injury in a side <b>Side</b> Tront s <b>Crash</b> Rear set   Based on the risk of injury in a side <b>Based on the risk of rollover in a side Based on the risk of rollover in a side</b> Star ratings range from 1 to 5   Source: National Highway	y.gov s and compare vehicles 5-STAR SAFETY t frontal, side and rollover. ter vehicles of similar size an ter vehicles of similar size an eat teat te impact. ter vehicles of similar size an eat teat te impact. ter vehicles of similar size an eat teat te impact. ter x + x + x + x + x + x + x + x + x + x
	RAMP ONE RU2G		OTAL MSRP \$30, Whether you decide to lea	,295.00	3F1	
	RAMP TWO ITEM #:   This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not in options or accessories are not	27-G385 O/T 5C Ford the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed Re	vehicle, you'll find the choi d Credit for you. See your dealer for www.ford.com/finance. SPECIAL ORDE C151 N RB 2X 425 006365 03	ices that are right r details or visit <b>ER</b>	WARNING: Operating, service vehicle can expose you to ch lead, which are known to the State To minimize exposure, avoid breath vehicle in a well-ventilated area and For more information go to www.P6	nemicals including engine ext of California to cause cancer ing exhaust. do not idle the e

05/20/2024

