| KAN-002107 _{TX} | 9-NORMAL,NB,202107,RA1 | 62 10466 220240123 | 3 0011 ULC CERT CERT | UWTRD RAMP BUMP CA | C AMP BOOK EXFL ROTA | 021320 2401/3277 |
|--------------------------|--|---|--|---|--|--|
| | CLE DESCRIPTION F-150 2024 F-150 4X4 REGU 122" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUT | LAR CAB EXT O TRANS FUNCTIONAL • AM/FM STEREO • BLIS W/CROSS-TRA • CLASS IV TRAILER H SMART TRLR TOW O • CURVE CONTROL MP, HOTSPOT TELEMAT • HILL START ASSIST | AFFIC ALERT HITCH W/ CONNECTOR HECT 5GWI-FI ICS MODEM STEM RAKING SIST W/AEB AND A A | JRITY AC™ WITH RSC® RONT SEAT DE IMPACT AFETY CANOPY® DUNT STOP LAMP ALARM RASH ALERT SYS™ SVCS: 1 YR PLAN JRE MONIT SYS UMPER / BUMPER OWERTRAIN OADSIDE ASSIST HYBRID BATTERY (MSRP) \$41,585.00 1,410.00 | Annual fuel COST \$2,850 | and Environ Standard Pickup Trucks 73 MPG. The best vehic MPGe. 24 highway uel Economy & Greenha 4 1 is vehicle emits 472 grams CO2 p tributing fuel also create emission cluding driving conditions and G and costs \$9.750 to fuel over cluding driving conditions and G and costs \$9.750 to fuel over cluding driving so reate emission cluding driving so reate cluding driving so reate so reate emission cluding driving so reate emission cluding driving drivi |
| | RAMP ONE | | TOTAL MSRP \$ | \$44,990.00 | Source: National Highway Traffic www.safercar.gov 1FTMF1L52 | Safety Administration (N or 1-888-327-4236 XRKD04841 |
| | CA7L RAMP TWO | CONVOY ITEM #: 52-2418 O/T 1 | Whether you decide | to lease or finance your ne choices that are right aler for details or visit | WARNING: Operating, servicing and r vehicle can expose you to chemicals in lead, which are known to the State of Californ | |
| | Information Disclose State and Local taxe | Dursuant to the Federal Automobile re Act. Gasoline, License, and Title Fees, s are not included. Dealer installed es are not included unless listed above. | SPECIAL ORDER RA162 N RB 2X 420 002107 01 16 24 | | Tead, which are known to the State of California to cause cancer and birth do To minimize exposure, avoid breathing exhaust, do not idle the engine exce vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle. | |

2202401230011

