U | W | TX | UTC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

	DESCRIPTION DGE 2024 EDGE TITANIUM AN 5-PASSENGER TWIN-SCRL 2.0L ECOBO 8-SPD AUTO TRANSMISS	OST ENG INT	<b>RB</b> TERIOR STONE BLUE METALLIC ERIOR CERAMIC ACTIVEX TRIMI	<b>328207</b> med sea	EPA DOT Fuel Economy and E Fuel Economy MPG Small S The bes
BELTLINE MOLDING- BRIGHT     EASY FUEL® CAPLESS FILLER     EXHAUST TIPS - STAINLESS     STEEL     FOG LAMPS-LED     GRILLE - CHROME     HEADLAMPS - AUTO HIGH BEAM     HEADLAMPS - AUTO HIGH BEAM     HEADLAMPS - LED WITH     SIGN LTG W/DARK BEZEL     LIFTGATE - HANDS-FREE     MIRRORS - PWR/HTD/MAN FOLD     LED SIG/APPROACH LAMP/MEM     PRIVACY GLASS - REAR DOORS     WIPERS - RAIN-SENSING  INCLUDED ON THIS VEHICLE     EQUIPMENT GROUP 300A     OPTIONAL EQUIPMENT/OTHER     2024 MODEL YEAR     STONE BLUE METALLIC     .19" NICKEL PTND ALUM WHLS     .245/55R19 A/S BSW TIRES     ROOF-RACK SIDE RAILS - SILVER     50 STATE EMISSIONS     MINI SPARE WHL/TIRE	INTERIOR • 110V/150W AC POWER OUTLET • 1TOUCH UP/DOWN DR/PASS V • 60/40 EASYFOLD REAR BENCH • AMBIENT LIGHTING • AUTO-DIM REARVIEW MIRROR • DUAL ILLUM VIS VANITY MIRR • DUAL-ZONE ELECTRONIC AUTO CLIMATE CONTROL • HTD LTHR WRAPPED STR WHI W/CRUISE AND AUDIO CTRLS • HTD, 10-WAY PWR PASS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • USB A AND C (MSRP) 495.00 165.00 NO CHARGE 100.00 NO CHARGE	VIN • FORD CO-PILOT360 I • FORDPASS™ CONN HOTSPOT TELEMAT • FORWARD SENSING • INTELL ACCESS W// • REAR PARKING SEN • REAR VIEW CAMER • REMOTE START SY • SIRIUSXM® W/360L	EM, 12 SPKR → ADVANC → AIRBAG NECT 4GWI-FI ICS MODEM G SYSTEM SOURS → AIRBAG → AIRBAG	000 BUMPER / BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST (MSRP) \$43,820.00 760.00	Image: Arrow and arrow an
	RAMP ONE RK34 RAMP TWO	RAIL ITEM #: 52-0232 O/T 2	TOTAL MSRP Whether you of vehicle, you'll Ford Credit for you. See yo www.ford.com	\$46,075.00 decide to lease or finance your find the choices that are right our dealer for details or visit n/finance.	2FMPK4K99RBB28207
	Information Disclosure State and Local taxes a	suant to the Federal Automobile Act. Gasoline, License, and Title Fees, re not included. Dealer installed are not included unless listed above.	RD091 N RB 2X 425		lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash y For more information go to www.P65Warnings.ca.gov/pass

05/30/2024

