KAN-004615 _{TX}	4-REBILL,NB,204615,RA302 135	563 220240118 BLEND	5698 ULC CERT CERT	UWTX TRD RAMP BUMP C	
VEHICLE DE Ford.com	E DESCRIPTION -150 2024 F-150 4X2 SUPERCREW 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO TRANS	EXTER CAN INTERI BLA AM/FM STEREO BLIS W/CROSS-TRAFFI CLASS IV TRAILER HITO SMART TRLR TOW CON CURVE CONTROL FORDPASS™ CONNEC HOTSPOT TELEMATICS HILL START ASSIST LANE-KEEPING SYSTEI POST-COLLISION BRAI PRE-COLLISION ASSIS REVERSE SENSING AN REAR VIEW CAMERA SELECTSHIFT® SYNC®4 W/EVR & 12" S	5698 CERT CERT CERT TRD RAMP BUMP() RK DOG571 RK DOG571 RIOR RBONIZED GRAY METALLIC OR ACK STX CLOTH 40/CON/40 STATUSCON CONTROLOGIO CONTROLOGIO ALRBAGS - FRONT SEAT MOUNTED SIDE IMPACT ALRBAGS - FRONT SEAT MOUNTED SIDE IMPACT ALRBAGS - SAFETY CANOPY® CERT HIGH MOUNT STOP LAMP PERIMETER ALARM SOS POST-CRASH ALERT SYSTM SOS POST-CRASH ALERT SYSTM STOLEN VEH SVCS: 1 YR PLAN STR/AG0,000 BUMPER / BUMPER STR/AG0,000 ROADSIDE ASSIST STR/AG0,000 ROADSIDE ASSIST STR/AG0,000 ROADSIDE ASSIST STR/AG0 OTIONS/OTHER STAL OTTAL OPTIONS/OTHER STAL STREE STINATION & DELIVERY		AMP BOOK EXFL ROTA A4449 AAA
3.15 RATIO REGULAR AXLE 6850# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS MOBILE OFFICE PACKAGE	NO CHARGE 535.00	CONVOY 52-Z102 O/T 2 Re Federal Automobile line, License, and Title Fees, uded. Dealer installed	TOTAL SAVINGS	.e.	Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size ar Frontal Driver Crash Passenger Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size ar Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover $\star \star \star \star$ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars ($\star \star \star \star \star$), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42 IFTEW2K51RKD06571 WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex- lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your b For more information go to www.P65Warnings.ca.gov/passenge

2202401185698

