KTP-000780 FL 9-NORMAL, NB, 000780, RD292 14565			CERT CERT CERT TRD RAMP BUMP	CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA 79	
	CLE DESCRIPTION SUPER DUT 2024 F250 SRW 4X4 CREW CA KING RANCH 160" WB STYLES 6.7 HI OUTPUT POWER STROM 10-SPEED AUTO TORQSHIFT	AB EXTERIOR SID STAR WHIT		California Air Resources Boar Environmer	
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • LED REFLECTOR HEADLAMPS • PICKUP BOX, TIE DOWN HOOKS • POWER SLIDING REAR WINDOW W/DEFROST & PRIVACY TINT • POWER TAILGATE • POWER TAILGATE • POWERSCOPE TT POWER-FOLD MIRRORS, POWER/HEATED • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER BRAKE CONTROL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER 2024 MODEL YEAR STAR WHITE DARKENED BRONZE ACCENT PREFERRED EQUIPMENT PKG.700A 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT 3.55 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET POWER RUNNING BOARDS 11100# GVWR PACKAGE 50 STATE EMISSIONS POWER MOONROOF TWIN PANEL HIGH CAPACITY TRAILER TOW PKG JACK WHEEL WELL LINERS FRONT & REAR TOUGH BED SPRAY IN BEDLINER MAX RECLINE DRIVER PASS SEAT	International statements in the statement is a statement in the statement in the statement in the statement is a statement in the statement in the statement in the statement is a statement in the s	BASE PRIC TOTAL OF TOTAL VE	BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGS LED CTR HIGH MNT STOP LAMP SECURICODE KEYLESS KEYPAD SOS POST-CRASH ALERT SYS™ WARRANTY '3YR/36,000 BUMPER / BUMPER '5YR/60,000 POWERTRAIN '5YR/60,000 DIESEL ENGINE (MSRP) FORMATION		
	RAMP ONE RH35 RAMP TWO ITEM #	RAIL	AL MSRP \$95,640.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right dit for you. See your dealer for details or visit www.ford.com/finance.	1FT8W2BM5RED89733	
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	soline, License, and Title Fees, cluded. Dealer installed RD292	N RB 2X 425 000780 04 29 24	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng	

