FLR-000202 OK 9	-NORMAL, NA, 100202, PL281 508	3 120231204 3688 BLEND 3688	CMC U W OK CERT CERT TRD RAMP BUMP	CAMPBOOKEXFLROTA 55
VEHICLE M M Ford.com STANDARD EQUIPMENT INCLUDED AT NO EXTERIOR • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - LED WITH SIGNATURE LIGHTING • MIRRORS - POWER GLASS/ MANUAL FOLD • TAILLAMPS-LED W/SEQUENTIAL TURN SIGNAL	DESCRIPTION USTANG 2024 ECOBOOST COUPE 4-PASSENGER SPORTS CAR 2.3L ECOBOOST 315HP 10-SPEED AUTOMATIC TRANS	EXTERIOR RAPID RED MI INTERIOR BLACK ONYX	R5 123422 ET TINTED CC CLOTH/VINYL TRIM SAFETY/SECURITY ADVANCETRAC™ESC AIRBAG-DRIVER/PASS KNEE AIRBAGS - DUAL STAGE FRONT AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SIDE AIR CURTAIN AIRBAGS - SIDE AIR CURTAIN BIDIV TIRE PRESS MONIT SYS LATCH CHILD SAFETY SYSTEM PERIMETER ALARM SECURILOCK PASS ANTI THEFT SOS POST CRASH ALERT SYS MUMPER AIRBAGOD BUMPER TO BUMPER SYR/60,000 POWERTRAIN SYR/60,000 ROADSIDE ASSIST (MSRP) RMATION DNS/OTHER ATOSION CLE & OPTIONS/OTHER 35,625.00	EPA DOT Fuel Economy Fuel Economy Subcompact Image: Subcompact of MPG Subcompact Image: Subcompact of Subcompact of Subcompact of MPG Subcompact Image: Subcompact of Subcomp
				Rollover Not Rate Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★★★★), with Source: National Highway Traffic Safety Administ
	RAMP ONE			www.safercar.gov or 1-888-327-423
	CA28	TOTAL	MSRP \$37,220.00 Whether you decide to lease or finance your	
	This label is affixed pursuant to th	52-Z800 O/T 2 Ford Credit	vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ext lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the e
	Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not in	line, License, and Title Fees, uded. Dealer installed PL281 N I	RA 2X 445 000202 11 28 23	vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

1202312043688

05/20/2024

