CHI-004838 NM	9-NORMAL,NB,104838,RB071 21	86 120240217 5779	UTCUWNMCERTCERTCERTTRDRAMPBUMP	CAMP BOOK EXFL ROTA 533/2
	CLE DESCRIPTION EXPLORER XLT 4WD 2024 EXPLORER XLT 4WD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSI	EXTERIOR ICONIC SILVE INTERIOR ION EBONY ACTIV	RG A34119 R METALLIC YEX SEAT MTRL	Fuel Economy and Envi Fuel Economy MPG. The best 20 27
<section-header><section-header><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></list-item></section-header></section-header>	<section-header> NTERIOR 110UCH UP/DOWN DR/PASS WIN 3RD ROW - 50/50 FOLD FLAT UAU ILLUM VIS VANITY MIRR RONT ROW HEATED SEATS CLUSTER 6.5" LCD SCREEN CHR WRAPPED STEERING WHI WMOUNTED CTRLS, TILT/TELE POWER DRIVER SEAT - 10 WAY POWER ORIVER SEAT - 10 WAY POWER ORIVER SEAT - 10 WAY TRI-ZONE ELECTRNC TMP CTRL USB A(1) AND C(1)-1ST ROW </section-header>		\$40,670.00	combined city/hwy city highway 4.3 gallons per 100 miles Annual fuel COSAT \$\$2,33500 Fuel Economy & Comparison \$\$4.3 \$\$2,33500 \$\$1 Image: State of the sta
	RAMP ONE	TOTAL	MSRP \$45,685.00	www.safercar.gov or 1-888-327-423 1FMSK8DH4RGA34119
	CA4B RAMP TWO ITEM # This label is affixed pursuant to Information Disclosure Act. Ga	56-2605 O/T 2 Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passen vehicle can expose you to chemicals including engine exha lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the en vehicle in a well-ventilated area and wear gloves or wash your had
	State and Local taxes are not in options or accessories are not	ncluded. Dealer installed RB071 N	RB 2X 425 004838 02 07 24	For more information go to www.P65Warnings.ca.gov/passenger-

1202402175779

