СНІ-005176 тх	9-NORMAL,NB,105176,RB071 <b>310</b>	120240218 0325	UTCUWTXCERTCERTCERTTRDRAMPBUMPCERTCERTCERTCERT	CAMPBOOKEXFLROTA 021773 1455/2337
VEHIC	ELE DESCRIPTION EXPLORER XLT RWD 2024 EXPLORER XLT RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	EXTERIOR AGATE BLAC INTERIOR BONY UNION FUNCTIONAL • 4-DR INTELL ACCESS LOCK/ UNLOCK W/PUSH-BUTTON START • AM/FM/MP3, 6 SPEAKERS • BRAKES, 4-WHEEL DISC/ABS • FORD CO-PILOT360™ • FORDPASS™ CONNECT • HILL START ASSIST • REAR PARKING SENSORS • REAR VIEW CAMERA • REFRESH95 • SIDE-WIND STABILIZATION • SIRIUSXM® - SVC N/A AK&HI • SYNC®3 8" SCRN W/APPLINK®	CERTICERTICERTI TRD RAMP BUMP( RG A40182 K METALLIC UE CLOTH SEATS SAFETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAG - DRIVER/PASS KNEE AIRBAGS - DUAL STAGE FRONT AIRBAGS - DUAL STAGE FRONT AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY SYSTEM™ CONVITED RESS MONIT SYST AIRBAGS - SAFETY SYSTEM™ CONVITED SIDE IMPACT BYR/36,000 BUMPER / BUMPER AIRBAGS - SAFETY SYSTEM™ AIRBAGS - SAFETY SYSTEM™ CONVITED SIDE IMPACT AIRBAGS - SAFETY SYSTEM™ AIRBAGS - SAFETY SYSTEM™ CONVITED SIDE IMPACT AIRBAGS - SAFETY SYSTEM™ AIRBAGS - SAFETY SYSTEM™ AIRBAGS - SAFETY SYSTEM™ CONVITED SIDE IMPACT AIRBAGS - SAFETY SYSTEM™ AIRBAGS - SAFETY SYSTEM™	AMP BOOK EXFL ROTA 21273 1455/2337   Image: Construction of the standard SUVs range for the
				Should ONLY be compared to other vehicles of similar size and weight.   Side Front seat   Crash Rear seat   Based on the risk of injury in a side impact.   Rollover   Based on the risk of rollover in a single-vehicle crash.   Star ratings range from 1 to 5 stars (*****), with 5 being Source: National Highway Traffic Safety Administration (N www.safercar.gov or 1-888-327-4236
	CH80	TOTAL	. MSRP \$40,145.00	1FMSK7DH5RGA40182
	RAMP TWO   ITEM #:     This label is affixed pursuant to th Information Disclosure Act. Gasol	e Federal Automobile line, License, and Title Fees,	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passenger vehicl vehicle can expose you to chemicals including engine exhaust, carbo lead, which are known to the State of California to cause cancer and birth do To minimize exposure, avoid breathing exhaust, do not idle the engine exce
	State and Local taxes are not inclu options or accessories are not inc	uded. Dealer installed RB071 N	RB 2X 425 005176 02 07 24	vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202402180325

