MIC-003571 _{TX}	9-NORMAL, NB, 103571, RE011 512	0 320240508 5079	ULC U W TX CERT CERT CERT TRD RAMP BUMP C	CAMPBOOKEXFLROTA 0 729
	BRONCO 2024 OUTER BANKS 4-DOOR 4X OUTER BANKS - 5 PASSENGER 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	ERUPTION GF INTERIOR	RL A56478 REEN METALLIC YL ROAST/BLK STS	EPA DOT Fuel Economy and Env Fuel Economy MPG Small SUVs The best ver
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • EASY FUEL® CAPLESS FILLER • FENDER TIE-DOWN HOOKS • GRILLE-BLK/BRONCO WHITE • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LED • TOW HOOKS-FRT (2)/REAR (1)	NO EXTRA CHARGE INTERIOR • 1TOUCH UP/DOWN DR/PASS WIN • 60/40 SPLIT FOLD REAR SEAT • A/C, DUAL ZONE CLIMATE CTL • CARPET FLOORING, BOTH ROWS • IP CLUSTER 8" DIGITAL SCRN • LEATHER-TRIM/VINYL SEATS • LOCKING GLOVE BOX • LTHR GEAR KNOB/STR WHEEL • POWERPOINTS - 12V • PWR 10-WAY DRV/8-WAY PASS • SMART CHARGING USB PORTS • TILT/TELESCOPE STR COLUMN	FUNCTIONAL • 12"LCD CTR STACK TOUCHSCRN • AUTO START STOP TECH • BRAKES, 4-WHEEL DISC/ABS • FORD CO-PILOT360™ • FORDPASS™ CONNECT • FRONT STABILIZER BAR • HILL START ASSIST • MID PACKAGE • PUSH-BUTTON START • SIRIUSXM® W/360L- NA AK&HI • SYNC®4 W/EVR • TER MGMT W/G.O.A.T. MODES® • TOOL KIT- DOOR/TOP REMOVAL	SAFETY/SECURITY • ADVANCETRAC [™] WITH RSC® • AIRBAGS-FRNT (DUAL STAGE) & SIDE IMPACT/SAFETY CANOPY® SYSTEM (ALL ROWS) • BELT-MINDER CHIME • CHILD SAFETY REAR DR LOCKS • ELCTR STABILITY/TRACTN CTL • INDIV TIRE PRESS MONIT SYS • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • PERSONAL SAFETY SYSTEM [™] MURRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN	 Low Low Low Low Low Low Low Low Low Low
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 314A •OUTER BANKS SERIES •HIGH/LUX PACKAGE •360-DEGREE CAMERA •ADAPTIVE CRUISE CONTROL •HEATED STEERING WHEEL •WIRELESS CHARGING PAD OPTIONAL EQUIPMENT/OTHER 2024 MODEL YEAR ERUPTION GREEN METALLIC P255/70R18 A/T TIRES (32") 4.27/REAR AXLE-LOCKING DIFF FRONT AXLE-OPEN DIFFRNTL AM/FM,10 SPKRS,SDARS CNCTD NAV (1-YEAR SUB INC) 18" MCHNED BLK-PNTD ALUM WHLS HARD TOP,GRAY MOLDED-IN-COLOR .SOUND DEADENING HEADLINER .FRT ROW TOP PANEL STORAGE BAG FRONT LICENSE PLATE BRACKET	(MSRP) 2,930.00 295.00 795.00 2,190.00 NO CHARGE		\$47,940.00	Actual results will vary for many reasons, including driving covehicle. The average new vehicle gets 28 MPG and costs \$9,75 based on 15,000 miles per year at \$3.60 per gallon. MPGe is memissions are a significant cause of climate change and smog. fueleconogygov Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Not Ra Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size at Frontal Driver Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size at Side Front seat Not Ra Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size at
AUXILIARY SWITCHES	195.00 RAMP ONE RPTB RAMP TWO ITEM #:	RAIL	and off-road adventure playground. Original Bronco owners who purchase and take delivery can attend this full-day, immersive driving experience, valued at \$2500. Fleet vehicles not eligible. See Roadeo.com for more information. MSRP \$56,240.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit	Crash Rear seat Not Rate Based on the risk of injury in a side impact. Rollover * * * Based on the risk of rollover in a single-vehicle crash. * * * * Star ratings range from 1 to 5 stars (* * * * * *), with Source: National Highway Traffic Safety Adminite www.safercar.gov or 1-888-327-44 1FMDE8BH7RLA56478 WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine expose you to chemicals ending the provement of
	This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not inclu- options or accessories are not inc	e Federal Automobile ine, License, and Title Fees, ded. Dealer installed RE011 N	www.ford.com/finance. RB 2X 435 003571 05 01 24	lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

3202405085079

06/03/2024

