KAN-002432 _{TX}	9-NORMAL, NB, 202432, RC182 108	220240325 4812	ULC U W TX CERT CERT CERT TRD RAMP BUMP C	C 02 CAMP BOOK EXFL ROTA 1513/
VEHI	CLE DESCRIPTION F-150 2024 F-150 4X2 SUPERCREW 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	EXTERIOR AGATE BLACK INTERIOR BLACK STX CO MART MSTEREO BLIS W/CROSS-TRAFFIC ALERT CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECTOR CURVE CONTROL FORDPASS™ CONNECT 5GWI-FI HOLS STM CONNECT 5GWI-FI HOLS STM CONNECT 5GWI-FI HUL START ASSIST LANE-KEEPING SYSTEM POST-COLLISION BRAKING PRE-COLLISION ASSIST W/AEB REVERSE SENSING AND REAR VIEW CAMERA SELECTSHIFT® SYNC®4 W/EVR & 12" SCREEN DASE PRICE TOTAL OPTION	RK D59486 METALLIC COTH 40/CON/40 SAFETY/SECURITY ADVANCETRAC™ WITH RSC® ANBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP PERIMETER ALARM SOS POST-CRASH ALERT SYS™ AIRB POST-CRASH ALERT SYS™ CTR PRESSURE MONIT SYS BIR/36,000 BUMPER / BUMPER SYR/60,000 POWERTRAIN SYR/60,000 ROADSIDE ASSIST BYR/100,000 HYBRID BATTERY MATION S48,230.00 NS/OTHER 48,230.00 MATION S48,230.00 SYOTHER 1,995.00	AMP BOOK EXEL (ROTA) 1513/ Image: Construction of the state of the s
				Star ratings range from 1 to 5 stars (★★★★), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-423
	RAMP ONE CH7L RAMP TWO ITEM #:	Fund	MSRP \$48,225.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit	1FTEW2KP9RKD59486
	This label is affixed pursuant to th Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inclu	e Federal Automobile line, License, and Title Fees, Ided. Dealer installed RC182 N I	www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ext lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the exposure vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

2202403254812

