Ford.com	VEHICLE DESCRIPTION EXPEDITIO 2024 EXPED. PLATINUM 4X PLATINUM 7-PASSENGER 3.5L ECOBOOST V6 ENGINE 10SPD AUTO TRANS W/SLO	2 EXTERIOR STONE E INTERIOR	RE A31	321	EPA DOT Fuel Economy and E Fuel Economy P 1 0 MPG Standard MPG. Th
STANDARD EQUIPMENT INCLUDE EXTERIOR • FWD FACING SPOTLIGHT-RH/LH • GRILLE-SILVER LINING MESH • HEADLAMPS -WIPER ACTIVATED • HEADLAMPS -WIPER ACTIVATED • HEADLAMPS -LED REFLECTOR W/LED SIGNATURE LIGHTING • MIRRORS-PWR/HTD/AUTO-FOLD SIG/APRCH LAMP/MEM/AUTODIM • PANORAMIC VISTA ROOF® • POWER LIFTGATE • ROOF-RACK SIDE RAILS-BRGHT • RUNNING BOARD-PWR DEPLOY • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING • ZONE LIGHTING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 600A OPTIONAL EQUIPMENT/OTHER 2024 MODEL YEAR STONE BLUE METALLIC · P285/45R22 A/S BSW TIRES BLUECRUISE EQUIP: 90 DAY TRIAL HEAVY-DUTY TRAILER TOW PKG 2ND ROW CAPTAIN CHAIR SEATS FLR LNERS RW 1&2 W/ CRPET MAT ROOF-RAIL CROSSBARS, BLACK 22" 6-SPK POLISHED ALUM WHLS FRONT LICENSE PLATE BRACKET	INTERIOR • 110V/150W AC POWER OUTLET • 2ND ROW HEATED SEATS • 2ND ROW PWR FOLDING TIP-AND-SLIDE SEATS • AMBIENT LIGHT/ILLUM ENTRY • HTD LTHR WRAPPED STR WHL	BASE TOTAL TOTAL	AIRBAGS - SAFETY (AIRBAGS - SIDE IMP AK INDIV TIRE PRESS M LATCH CHILD SAFE 2.0 PERIMETER ALARM /I-FI PERSONAL SAFETY EM REAR OCCUPANT A SOS POST-CRASH A HI RN <u>WARRANTY</u> 3YR/36,000 BUMPEF 5YR/60,000 POWERT 5YR/60,000 ROADSII	/ITH RSC® TAGE FRONT CANOPY® PACT MONIT SYS TY SYSTEM SYSTEM™ LERT ALERT SYS™ R / BUMPER TRAIN	Image: Additional and the construction of the construc
	This label is affixed pursuar	RAIL 52-M104 O/T 2	Whether you decide to leas vehicle, you'll find the choic	ces that are right	Crash Rear seat Based on the risk of injury in a side impact. Rollover ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★ ★), Source: National Highway Traffic Safety Adm www.safercar.gov or 1-888-327 IFMJK1L86REA31321 WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle to vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passed

