KTP-000370 _{CA}	71A 040 6B 2 X LABL ADJ COV PRCS B	B10 RAMP BUMP 1FT7W2BA0	REC43077 SUPER	MAIL	018 402,
	SUPER DUTY 2024 F250 SRW 4X4 CREW CAI XL 176" WB STYLESIDE		RE C43077		
ford.com STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT	6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-G	INTERIOR	XK SLATE VINYL SAFETY/SECURITY • ADVANCETRAC™ WITH RSC® • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • DRIVER/PASSENGER AIR BAGS • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS™ WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 POWERTRAIN • 5YR/60,000 DIESEL ENGINE	These ratings are no For informa	environment. Cho s Rating (tailpipe only D
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G 3.73 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET 10000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SNOWPLOW PREP/CAMPER PACKAGE SPARE TIRE AND WHEEL JACK	(MSRP) NO CHARGE NO CHARGE NO CHARGE 175.00 305.00 NO CHARGE		\$51,770.0		bard based on this vehicle T 5-STAR SAFETY F re Not Rate
UPFITTER SWITCHES 250 AMP ALTERNATOR XL CHROME PACKAGE .FOG LAMPS				Frontal CrashDriver PasseBased on the risk of injury in a fi Should ONLY be compared to orSide CrashFront Rear s Based on the risk of injury in a s Based on the risk of rollover in aRollover Based on the risk of rollover in a	enger Not Rate frontal impact. other vehicles of similar size and seat Not Rate side impact. Not Rate
	RAMP ONE RU84	TOTAL	. MSRP \$54,720.00	Star ratings range from 1 to Source: National Highwa www.safe	-
	RAMP TWO	71-2091 O/T 59 Ford Credit The Federal Automobile Soline, License, and Title Fees, Uded. Dealer installed R835 R	Whether you decide to lease or finance you vehicle, you'll find the choices that are righ for you. See your dealer for details or visit www.ford.com/finance. SPECIAL ORDER 6B 2X 420 000370 12 21 23	nt MADNING Operating our	e of California to cause cancer a athing exhaust, do not idle the er nd wear gloves or wash your ha

05/03/2024

