ford.com	2024 EXPEDITION LIMIT LIMITED 7-PASSENGER 3.5L ECOBOOST V6 ENG 10SPD AUTO TRANS W/S	ED 4X4 E	KE XTERIOR STAR WHITE MET TRI-C ITERIOR SANDSTONE LEATHER-1		EPA DOT Fuel Economy and E Fuel Economy MPG Standard MPG. TI
ford.com STANDARD EQUIPMENT INCLUDED ACOUSTIC-LAMINATE WINDSHLD ACTIVE GRILLE SHUTTERS DOOR HANDLES - BODY COLOR W/BRIGHT INSERTS EASY FUEL® CAPLESS FILLER HEADLAMPS-LED REFLECTOR W/LED SIGNATURE LIGHTING PANORAMIC VISTA ROOF® POWER LIFTGATE PRIVACY GLASS - REAR DOORS ROOF-RACK SIDE RAILS-BRGHT TAILLAMPS/FOG LAMPS - LED TRAILER SWAY CONTROL WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 302A RUNNING BOARDS, POWER DEPLOY -22" 12-SPK POLISHED ALUM WHL OPTIONAL EQUIPMENT/OTHER STAR WHITE MET TRI-COAT .P285/45R22 A/S BSW TIRES HEAVY-DUTY TRAILER TOW PKG 2ND ROW CAPTAIN CHAIR SEATS 15.5 LCD SCREEN W/TOUCH CAP FRONT LICENSE PLATE BRACKET		FUNCTIONAL • 4-DR INTELL ACC UNLOCK W/PUSH • ACTIVE NOISE CO G • B&O SOUND SYS LS • CLASS IV TRLR T • CNCTD NAV (1-YI • FORD CO-PILOTC • FORDPASS™ CO HOTSPOT TELEM • HD RADIO™ • INTELLIGENT 4W WS • REMOTE START L • SIRIUSXM® W/36	SAFETY SESS LOCK/ • ADVAN I-BUTTON START • AIRBA DNTROL • AIRBA TEM, 12 SPKR • AIRBA OW PREP PAK • LATCH R TRIAL) • PERIM 960™ ASSIST+ • PERSC NNECT 4GWI-FI • REAR ATICS MODEM • SECUF • SECUF D SYSTEM • SOS P SYSTEM 90L- NA AK&HI • WARRA GING PAD • 5YR/60	X/SECURITY NCETRAC™ WITH RSC® GS - DUAL STAGE FRONT GS - SAFETY CANOPY® GS - SIDE IMPACT I CHILD SAFETY SYSTEM I CHILD SAFETY SYSTEM ICHILD SAFETY SYSTEM™ OCCUPANT ALERT RICODE KEYLESS KEYPAD RILOCK® ANTI-THEFT SYS OST-CRASH ALERT SYS™ NO00 BUMPER / BUMPER 0,000 POWERTRAIN 0,000 ROADSIDE ASSIST (MSRP) \$74,410.00 5,490.00 NS/OTHER 79,900.00	Image: A start of the second secon
	RAMP ONE RK34 RAMP TWO	RAIL ITEM #: 52-1112 O/T 2	- <i>Fired</i> vehicle vou'l	decide to lease or finance your I find the choices that are right your dealer for details or visit	1FMJK2A88REA49859
	Information Disclosure State and Local taxes an	suant to the Federal Automobile Act. Gasoline, License, and Title Fe re not included. Dealer installed are not included unless listed above	s, RC071 N RB 2X 425		lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passo

