Ford.com	HICLE DESCRIPTION EXPEDITION 2024 EXPED. LTD STEALTH 4X4 LIMITED 7-PASSENGER 3.5L ECOBOOST V6 ENGINE 10SPD AUTO TRANS W/SLCTSH	4 EXTERIOR DARK MATTI INTERIOR	RE A03310 ER PC EATHER-TRIM SEATS	EPA DOT Fuel Economy and E Fuel Economy MPG. T
STANDARD EQUIPMENT INCLUDED EXTERIOR • ACOUSTIC-LAMINATE WINDSHLD • ACTIVE GRILLE SHUTTERS • EASY FUEL® CAPLESS FILLER • HEADLAMPS -WIPER ACTIVATED • HEADLAMPS-LED REFLECTOR W/LED SIGNATURE LIGHTING • PANORAMIC VISTA ROOF® • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 303A • STEALTH EDITION PACKAGE	AT NO EXTRA CHARGE PAT NO EXTRA CHARGE NIT IN COMPACT OF A COMPACT O		AIRBAGS - SAFETY CANOPY® AIRBAGS - SIDE IMPACT LATCH CHILD SAFETY SYSTEM PERIMETER ALARM PERSONAL SAFETY SYSTEM™ REAR OCCUPANT ALERT SECURICODE KEYLESS KEYPAD SECURILOCK® ANTI-THEFT SYS SOS POST-CRASH ALERT SYS™ WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST (MSRP) DRMATION S71,410.00 IONS/OTHER 9,455.00	Calculate personalized estimates and compare vehicle
.22" BLACK-PNTD ALUM WHEELS P285/45R22 A/S BSW TIRES RUN BOARDS, BLK-PWR DEPLOY BLACK HEADLAMP ACCENTS 2ND ROW CAPTAIN CHAIR SEATS HEAVY-DUTY TRAILER TOW PKG CCD W/SPORT TUNING SUSP CONTROLTRAC WITH 3.73 ELSD 15.5 LCD SCREEN W/TOUCH CAP FRONT LICENSE PLATE BRACKET	NO CHARGE 995.00 1,495.00 1,500.00 795.00 NO CHARGE		ICLE & OPTIONS/OTHER 80,865.00 N & DELIVERY 1,895.00	
	RAMP ONE RA84 RAMP TWO ITEM #: 7	RAIL	L MSRP \$82,760.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	IFMJU2A80REA03310 WARNING: Operating, servicing and maintaining a vehicle can expose you to chemicals including engilead, which are known to the State of California to cause c
	This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inc	pline, License, and Title Fees, uded. Dealer installed PJ182 N	RB 2X 415 000262 09 18 23	Tead, which are known to the State of California to cause c To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash y For more information go to www.P65Warnings.ca.gov/pass

05/20/2024

