| KTP-000087 _{TX} | 9-NORMAL, NB, 200087, RB222 11 | 887 | ULCUWTXCERT CERT CERTTRDRAMPBUMP | |
|--|---|---|---|---|
| VEH VEH VEH VEH VEH VEH VEH VEH | CLE DESCRIPTION EXCLAPTION EXCLAPTION EXCLAPTION EXCLAPTION CALCERNIE ACTION ACTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION EXCLAPTION CLE DESCRIPTION EXCLAPTION | EXTERIOR STAR WHITE INTERIOR LGHT SANDS CHFT EUNCTIONAL 9 360-DEGREE CAMERA 9 ACTIVE NOISE CONTROL 9 ADVANCED CARGO MANAGER 9 AUDIO - REAR SEAT CONTROLS 9 & OUNLEASHED, 22 SPKR 9 CLASS IV TRLR TOW PREP PAK 9 | CERTICERTICERTI TRD RAMP BUMP RE A29495 MET TRI-COAT MET TRI-COAT TONE LEATHER-TRM | EPA DOT Fuel Economy Fuel Economy Fuel Economy Fuel Economy MPG Standard SU MPG MPG Mpd MPG Mpd MPG Mpd MPG Mpd Mpd Mpd Mpd Mpd Mpd Mpd Mpd Mpd Mpd Mpd Mpd |
| FRONT LICENSE PLATE BRACKET | NO CHARGE | | | Frontal CrashDriver PassengerImage: CrashBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size arSide CrashFront seat Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.RolloverBased on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42 |
| | RAMP ONE RH80 | | MSRP \$86,155.00 Whether you decide to lease or finance your | 1FMJU1L84REA29495 |
| | This label is affixed pursuant to Information Disclosure Act. Ga | 52-M114 O/T 2 Ford Credit | vehicle, you'll find the choices that are right t for you. See your dealer for details or visit www.ford.com/finance. | WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the |
| | State and Local taxes are not in options or accessories are not | cluded. Dealer installed RB222 N | RB 2X 425 000087 02 22 24 | vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge |

06/01/2024

