CHI-003661 <sub>CA</sub>	9-NORMAL,NB,103661,RB151 920	120240224 6358	UTC U W CA CERT CERT CERT TRD RAMP BUMP (	CAMPBOOKEXFLROTA 02
	ELE DESCRIPTION EXPLORER XLT RWD 2024 EXPLORER XLT RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSIO	EXTERIOR STAR WHITE N INTERIOR N EBONY UNIQU	RG A49981 NET TRI-COAT E CLOTH SEATS	EPA DOT Fuel Economy and Env Fuel Economy MPG. The best 21 29
<section-header><section-header><section-header></section-header></section-header></section-header>	<section-header>INTERIOR 9.110LCH UP/DOWN DR/PASS WIN 9.3RD ROW - 50/50 FOLD FLAT 1.04AL ILLUM VIS VANITY MIRR 1.4ATED CLOTH FRONT SEATS 1.9 CLUSTER 6.5" LCD SCREEN 1.4ATHER WRAPPED STR WHEEL 2. POWER DRIVER SEAT - 10 WAY 2. POWER PASS SEAT - 4-WAY 2. POWERPOINTS - 12W 3.000 STEERING 3.000 STEERING STEERING 3.000 CHARGE 3.000 3.000</section-header>	<ul> <li>FUNCTIONAL</li> <li>4-DR INTELL ACCESS LOCK/ UNLOCK W/PUSH-BUTTON START.</li> <li>AM/FM/MP3, 6 SPEAKERS</li> <li>BRAKES, 4-WHEEL DISC/ABS</li> <li>FORD CO-PILOT360™</li> <li>FORD CO-PILOT360™</li> <li>FORD PASS™ CONNECT</li> <li>HILL START ASSIST</li> <li>REAR PARKING SENSORS</li> <li>REAR VIEW CAMERA</li> <li>REFRESH95</li> <li>SIDE-WIND STABILIZATION</li> <li>SIRIUSXM® - SVC N/A AK&amp;HI</li> <li>SYNC®3 8" SCRN W/APPLINK®</li> </ul>	\$38,670.00 NS/OTHER 675.00 LE & OPTIONS/OTHER 39,345.00	Image: Angle of the second
	RAMP ONE CA84 RAMP TWO		Nhether you decide to lease or finance your	www.safercar.gov or 1-888-327-423
	This label is affixed pursuant to the Information Disclosure Act. Gase State and Local taxes are not incluing options or accessories are not incluing	72-7447 O/T 2 The Federal Automobile Sline, License, and Title Fees, uded. Dealer installed RB151 N	vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. RB 2X 425 003661 02 15 24	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the e vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger

