| OHI-000032 _{WI} | 41C 066 6B 2 X LABL ADJ COV PRC | S B10 RAMP BUMP 1FDTF | '4HT6PDA10886 SU | JPER | MAIL |
|--|--|--|---|---|---|
| | CLE DESCRIPTION SUPER DUT 2023 F450 4X4 REG CHASSI XL 145" WB CHASSIS CAB 6.7L POWER STROKE V8 DII 10-SPEED AUTO TORQSHIF | IS EXTERIOR OXFORI ESEL INTERIOR | PD A10 d white m dark slate vinyl | 886 | EPA DOT Fuel Economy and E FUEL ECONO |
| STANDARD EQUIPMENT INCLUDED A EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.650A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT 225/70R19.5G BSW MAX TRAC TIRE 4.10 RATIO LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS FORD PRO UPFIT INTEGR REMOVAL 16000# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS 120V/400W OUTLET SNOW PLOW PREP PACKAGE SPARE TIRE AND WHEEL DELETE JACK | AT NO EXTRA CHARGE INTERIOR 4.2" PRODUCTIVITY SCREEN AIR COND, MANUAL FRONT BLACK VINYL FLOOR COVERING OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS UPFITTER SWITCHES 9,995.00 NO CHARGE 215.00 395.00 NO CHARGE 320.00 - 400.00 100.00 NO CHARGE 175.00 250.00 - 85.00 55.00 | FUNCTIONAL • 4-WHEEL ANTILOCK BRAKE • FORDPASS™ CONNECT 5G HOTSPOT TELEMATICS MOI • HILL START ASSIST • JEWEL EFFECT HEADLAMP • REMOTE KEYLESS ENTRY • STABILIZER BAR, FRONT/RI • SYNC®4 W/8" SCREEN PRIC BASE TOTA | SAFETY/SECURITY SYS • ADVANCETRAC™ V WI-FI • AIRBAGS - SAFETY DEM • BELT-MINDER CHII • DRIVER/PASSENGE • DRIVER/PASSENGE S • SECURILOCK® ANT • SOS POST-CRASH | Z CANOPY® ME ER AIR BAGS TI-THEFT SYS ALERT SYS™ ER / BUMPER RTRAIN IDE ASSIST | FUEL ECONO REQUIRED C |
| 350 AMP ALTERNATOR PAYLOAD DOWNGRADE PACKAGE DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE .FOG LAMPS .BRIGHT GRILLE .REMOTE START SYSTEM | NO CHARGE NO CHARGE 415.00 225.00 RAMP ONE CP07 RAMP TWO | CONVOY | Whether you decide to lea | ices that are right | IFDTF4HT6PDA10886 Image: Servicing and maintaining a provide the service of California to cause cause and which are known to the State of California to cause and service and which are known to the state of California to cause and service and which are known to the state of California to cause and service and which are known to the state of California to cause and service and which are known to the state of California to cause and service and which are known to the state of California to cause and service and which are known to the state of California to cause and service and |

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

06/05/2024

R789 R 6B 2X 350 000032 10 18 23

SPECIAL ORDER

Environment

DMY RATINGS NOT ON THIS VEHICLE





The FordPass® Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977-2022 CY total sales. **FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.



FORD **PROTECT***



Insist on Ford Protect! The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit www.FordOwner.com.

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

SCAN OR TEXT 1FPDA10886 TO 48028

Msg & Data rates may apply. Text HELP for help



www.ford.com/help/privacy-terms/