KTP-000363 _{TX}	52A 241 6B 2 X LABL ADJ COV PRCS B10	RAMP BUMP 1FDRF3GT9RED21523	SUPER	MAIL	023 379/
	CLE DESCRIPTION SUPER DUTY 2024 F350 DRW 4X2 REG CHAS XL 169" WB CHASSIS CAB 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT	RE EXTERIOR OXFORD WHITE INTERIOR MEDIUM DARK SLATE V	D21523		vironment
STANDARD EQUIPMENT INCLUDED A EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT	INTERIOR FU • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERING • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE,	4-WHEEL ANTILOCK BRAKE SYS FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST JEWEL EFFECT HEADLAMPS REMOTE KEYLESS ENTRY STABILIZER BAR, FRONT/REAR SYNC®4 W/8" SCREEN WARRA - 3YR/3 - 5YR/6	//SECURITY NCETRAC [™] WITH RSC® .GS - SAFETY CANOPY® MINDER CHIME R/PASSENGER AIR BAGS RILOCK® ANTI-THEFT SYS OST-CRASH ALERT SYS [™] .NTY 6,000 BUMPER / BUMPER 0,000 POWERTRAIN 0,000 ROADSIDE ASSIST 00,000 DIESEL ENGINE	For informa	C- D
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.640A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT 4 NO RATIO LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET 14000# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS SPARE TIRE AND WHEEL DELETE JACK 40 GAL AFT OF AXLE FUEL TNK EXTRA HEAVY SERVICE SUSPENSION DUAL BATTERY REAR VIEW CAMERA & PREP KIT	(MSRP) 9,995.00 NO CHARGE 395.00 NO CHARGE - 85.00 55.00 NO CHARGE 125.00 NO CHARGE 415.00	PRICE INFORMATION BASE PRICE TOTAL OPTIONS/OTHER TOTAL VEHICLE & OPTION DESTINATION & DELIVERY		California Air Resources Boa	
	ITEM #:	899 O/T 59 Special vehicle, you' Ieral Automobile for you. See License, and Title Fees, SPECIA Dealer installed R943 R 6B 2X 425	decide to lease or finance your Il find the choices that are right your dealer for details or visit m/finance.	For more information go to www.Put	DRF3GT9RED21523 icing and maintaining a passent hemicals including engine exha of California to cause cancer a hing exhaust, do not idle the end d wear gloves or wash your har 65Warnings.ca.gov/passenger-v

