| FLR-000214 <sub>CA</sub>   | 9-NORMAL, NA, 100214, RE031 560  | 0 120240520 099   | 5 CMC U<br>CERT CERT CERT TRD 1  | W CA<br>RAMP BUMP C.   | AMP BOOK EXFL ROTA   | 02<br>138  |
|--|--|---|--|--|--|--|
|  | LE DESCRIPTION<br><b>SUBSTANG</b><br>2024 ECOBOOST COUPE<br>4-PASSENGER SPORTS CAR<br>2.3L ECOBOOST 315HP<br>10-SPEED AUTOMATIC TRANS<br><b>IND EXTRA CHARGE</b><br><b>INTERIOR</b><br>- 12.4" LCD DIG INSTR CLUSTE  | INTERIOR  | R5 1378<br>D MET TINTED CC<br>NYX CLOTH/VINYL TRIM<br>SAFETY/SECURITY<br>R • ADVANCETRACTMESC                                      | 90   | EPA<br>Fuel Economy<br>Fuel Economy<br>MPG<br>226<br>22combined city/hwy   |  |
| <ul> <li>HEADLAMPS - AUTOLAMP<br/>(ON/OFF)</li> <li>HEADLAMPS- LED WITH<br/>SIGNATURE LIGHTING</li> <li>MIRRORS - POWER GLASS/<br/>MANUAL FOLD</li> <li>TAILLAMPS-LED W/SEQUENTIAL<br/>TURN SIGNAL</li> <li>WIPERS - RAIN-SENSING</li> </ul> | <ul> <li>13.2" LCD CENTERSTACK<br/>SCREEN</li> <li>1TOUCH UP/DOWN DR/PASS WIN</li> <li>CENTER CONSOLE W/ARMREST</li> <li>FLAT BOTTOM STRG WH - VNYL</li> <li>SMART CHARGING USB PORT(2)</li> <li>SPLIT FOLD REAR SEAT</li> <li>TILT/TELESCOPE STR COLUMN</li> <li>WINDOWS - GLOBAL OPEN</li> </ul> | <ul> <li>FORD CO-PILOT360™</li> <li>FORDPASS™ CONNECT 4GWI-</li> <li>INDEPENDENT REAR SUSPEN</li> <li>INTELLIGENT ACCESS W/PUSI-<br/>BUTTON START</li> <li>LIMITED SLIP REAR AXLE</li> <li>REAR PARKING SENSORS</li> <li>REAR VIEW CAMERA</li> <li>SELECTABLE DRIVE MODES</li> <li>SYNC®4</li> <li>TRACK APPS™</li> </ul> | AIRBAG-DRIVER/PASS     AIRBAGS - DUAL STAG     AIRBAGS - FRONT SEA   | GE FRONT<br>AT<br>CT<br>URTAIN<br>NIT SYS<br>SYSTEM<br>NTI THEFT<br>ERT SYS<br>O BUMPER<br>AIN | <b>\$2,100</b>   | uel Economy &<br>1<br>is vehicle emits 341 gr<br>stributing fuel also creat<br>cluding driving cond<br>g and costs \$9.750 |
| INCLUDED ON THIS VEHICLE<br>EQUIPMENT GROUP 101A<br>•DUAL-ZONE ELEC AUTO TEMP CTRL<br>•SIRIUSXM W/ 360L  | (MSRP)<br>2,600.00   | BASE PF   | <b>NFORMATION</b><br>RICE<br>OPTIONS/OTHER   | (MSRP)<br>\$30,920.00<br>3,990.00  | Actual results will vary for many reasons, inc<br>vehicle. The average new vehicle gets 28 MP<br>based on 15,000 miles per year at \$3.60 per g<br>emissions are a significant cause of climate of<br>fueleconomy.go<br>Calculate personalized estimates and com | V  |
| OPTIONAL EQUIPMENT/OTHER<br>2024 MODEL YEAR<br>RAPID RED MET TINTED CC<br>.3.15 RATIO LIMITED SLIP AXLE<br>255/40R19 W-RATED TIRE<br>SPOILER DELETE<br>19X8.5 PREMIER POLISHED ALUM<br>FRONT LICENSE PLATE BRACKET                           | 495.00<br>NO CHARGE<br>895.00<br>NO CHARGE   |   | TEHICLE & OPTIONS/OTHER  | 34,910.00<br>1,595.00  | GOVERNMENT 5-STA<br>Overall Vehicle Score<br>Based on the combined ratings of frontal, s<br>Should ONLY be compared to other vehicle   | Not Rate   |
|  |  |   |  |  | Frontal<br>CrashDriver<br>PassengerBased on the risk of injury in a frontal impar<br>Should ONLY be compared to other vehicle  | Not Rate<br>Not Rate<br>ct.<br>ss of similar size and  |
|  |  |   |  | SideFront seatCrashRear seatBased on the risk of injury in a side impact.Rollover              | Not Rate<br>Not Rate   |  |
|  |  |   |  |  | Based on the risk of rollover in a single-veh<br>Star ratings range from 1 to 5 stars (<br>Source: National Highway Traffic<br>www.safercar.gov  | icle crash.<br>★ ★ ★ ★ ★ ), with<br>Safety Adminis   |
|  | RAMP ONE<br>RA84   | тот   | AL MSRP \$36,5   |  |  | 2R5137890  |
|  | RAMP TWO   | RAIL Ford Cru   | Whether you decide to lease c<br>vehicle, you'll find the choices<br>edit for you. See your dealer for de<br>www.ford.com/finance. | that are right   | WARNING: Operating, servicing and r<br>vehicle can expose you to chemicals i<br>lead, which are known to the State of Californ   | naintaining a passe<br>ncluding engine exh<br>nia to cause cancer  |
|  | This label is affixed pursuant to t<br>Information Disclosure Act. Gas<br>State and Local taxes are not inc<br>options or accessories are not in   | oline, License, and Title Fees,<br>Iuded. Dealer installed <b>RE03</b>  | 1 N RA 2X 470 000214 05 03   | 3 24   | To minimize exposure, avoid breathing exhall vehicle in a well-ventilated area and wear glo For more information go to www.P65Warning  | ist. do not idle the e   |

## 1202405200995

05/22/2024

