Ford.com		RK E16083 EXTERIOR CARBONIZED GRAY METALLIC INTERIOR DARK SLATE CLOTH 40/CON/40		EPA DOT Fuel Economy and En	
				Fuel Economy	
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FOG LAMPS-LED • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • POWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT • ZONE LIGHTING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 302A • XLT SERIES • LED SIDE-MIRROR SPOTLIGHTS • POWER-SLIDING REAR WINDOW OPTIONAL EQUIPMENT/OTHER .EXTENDED RANGE 36GAL FUEL TAN 5.0L V8 ENGINE 265/60R18 BSW ALL-SEASON 3.15 RATIO REGULAR AXLE 6850# GVWR PACKAGE FRONT LICENSE PLATE BRACKET ENGINE BLOCK HEATER 50 STATE EMISSIONS BLUECRUISE EQUIP: 90DAY TRIAL MIRROR MAN FOLD W/POWER GLASS 18" CHROME-LIKE PVD WHEELS TX BADGE	SUBJECTION OF CONTRACT OF CONT	BASE TOTA TOTA DEST TOT XLT	V/ • AIRBAGS - FRONT MOUNTED SIDE IN WI-FI • AIRBAGS - SAFET • CTR HIGH MOUNT • PERIMETER ALAR • SECURICODE KEY AEB • SOS POST-CRASH SIST • STOLEN VEH SVC • TIRE PRESSURE N • WARRANTY • 3YR/36,000 BUMP • 5YR/60,000 POWE	WITH RSC® T SEAT MPACT 'Y CANOPY® T STOP LAMP RM YLESS KEYPAD H ALERT SYS™ S: 1 YR PLAN MONIT SYS PER / BUMPER ERTRAIN SIDE ASSIST	Should ONLY be compared to other vehicles of similar size Frontal Driver Crash Passenger Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Based on the risk of injury in a side impact. Based on the risk of injury in a side impact. Rollover Star ratings range from 1 to 5 stars (*****), w Source: National Highway Traffic Safety Admin
	ITEM #:	CONVOY	OTAL MSRP \$50 Whether you decide to le vehicle, you'll find the ch for you. See your dealer f www.ford.com/finance.	nices that are right	www.safercar.gov or 1-888-327- 1FTEW3K54RKE16083 WARNING: Operating, servicing and maintaining a pa vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can
	This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not includ options or accessories are not incl	ne, License, and Title Fees, led. Dealer installed RE	E012 N RB 2X 440 003576 (05 01 24	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer

