U W NY UTC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

Ford.com	IICLE DESCRIPTION EDGE 2024 EDGE SEL AWD 5-PASSENGER TWIN-SCRL 2.0L ECOBOOST E 8-SPD AUTO TRANSMISSION	EXTERIOR AGATE BLAC ENG INTERIOR EBONY ACTIV		EPA DOT Fuel Economy and E Fuel Economy MPG Small SL The best
STANDARD EQUIPMENT INCLUDED EXTERIOR • BELTLINE MOLDING- BRIGHT • DOOR HANDLES - BODY COLOR • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - LED WITH SIGN LTG W/DARK BEZEL • MIRRORS-HTD/POWER GLASS, MANUAL FOLD • PRIVACY GLASS - REAR DOORS • REAR WIPER/WASHER/DEFROST • TAILLAMPS-LED INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 201A	AT NO EXTRA CHARGE INTERIOR • 1TOUCH UP/DOWN DR/PASS WIN • 60/40 EASYFOLD REAR BENCH • 0UTO-DIM REARVIEW MIRROR • CUPHOLDERS - 8 • DUAL ILLUM VIS VANITY MIRR • DUAL-ZONE ELECTRONIC AUTO CLIMATE CONTROL • POWERPOINTS - 12W • ROTARY GEAR SHIFT DIAL • SEATS-HTD, 8-WAY PWR DRV & 4-WAY PWR PASS • USB A AND C	 EUNCTIONAL AM/FM/MP3, 6 SPEAKERS AUTO START STOP TECH ELECTRONIC PWR ASST STEER PORD CO-PILOT360™ FORDPASS™ CONNECT 4GWI-FI HOTSPOT TELEMATICS MODEM INTELL ACCESS W/PUSH START REAR PARKING SENSORS REAR VIEW CAMERA SIRIUSXM® W/360L- NA AK&HI SYNC®4A W/EVR & 12" SCREEN 		fuelesenenygev
OPTIONAL EQUIPMENT/OTHER .18" SPLT-SPK SLVR PTD ALUM WH 245/60118 A/S BSW TIRES HEATED STEERING WHEEL FLR LINERS, FRT/RR W/CARPET CONVENIENCE PACKAGE .PERIMETER ALARM .POWER LIFTGATE .REMOTE START SYSTEM .UNIVERSAL GARAGE DOOR OPENER .WIRELESS CHARGING PAD 50 STATE EMISSIONS PANORAMIC VISTA ROOF MINI SPARE WHL/TIRE FRONT LICENSE PLATE BRACKET	350.00 200.00 1,250.00 NO CHARGE 1,595.00 100.00 NO CHARGE			Calculate personalized estimates and compare vehicles
	RAMP ONE CV60 RAMP TWO ITEM #:	CONVOY	MSRP \$44,655.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not in options or accessories are not	soline, License, and Title Fees, cluded. Dealer installed RD081 N	RB 2X 425 000271 04 08 24	Tead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash y For more information go to www.P65Warnings.ca.gov/pass

