| CHI-004738 FL   | 9-NORMAL,NB,104738,PL291   | 2199 120231210 7297                              | UTCUWFLCERTCERTCERTTRDRAMPBUMP   | CAMP BOOK EXFL ROTA 857/987  |
|---|--|--|--|--|
| VEH<br>VEH<br>VEH<br>VEH<br>VEH<br>VEH<br>VEH<br>VEH        | <section-header>CLE DESCRIPTION<br/>EXAMPLE A CALL A CONSTRUCTION<br/>CALL A CONSTRUCTION<br/>CALL A CONSTRUCTION<br/>CALL A CONSTRUCTION<br/>A CONSTRUCTION<br/>CALL A CONSTRUCTION<br/>CALL A</section-header> | EXTERIOR<br>ICONIC SILV<br>INTERIOR<br>EBONY ACT | CERT CERT CERT TRD RAMP BUMP<br>PG B95086<br>CER METALLIC<br>VEX SEAT MTRL<br>MARY SEA | EPA<br>Fuel Economy<br>Fuel Economy<br>MPG<br>MPG<br>MPG<br>MPG<br>MPG<br>MPG<br>MPG<br>MPG<br>MPG<br>MPG  |
| 4G LTE WI-FI HOTSPOT CREDIT<br>REAR AUXILIARY CNTRLS CREDIT | - 20.00<br>- 100.00  |  | L MSRP \$43,785.00   | Frontal Driver * * * * * * * * *   Crash Passenger * * * * * * * * *   Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and weight.   Side Front seat * * * * * * * * *   Crash Rear seat * * * * * * * *   Based on the risk of injury in a side impact. * * * * * * * * *   Based on the risk of injury in a side impact. * * * * * * * * *   Based on the risk of injury in a side impact. * * * * * * * *   Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (* * * * *), with 5 being Source: National Highway Traffic Safety Administration (N www.safercar.gov or 1-888-327-4236   IFMSK7DH9PGB95086 IFMSK7DH9PGB95086 |
|   | CA14   | CONVOY   | Whether you decide to lease or finance your<br>vehicle, you'll find the choices that are right<br>for you. See your dealer for details or visit<br>www.ford.com/finance.   | WARNING: Operating, servicing and maintaining a passenger vehic<br>vehicle can expose you to chemicals including engine exhaust, carb<br>lead, which are known to the State of California to cause cancer and birth d  |
|   | State and Local taxes are no   | Gasoline, License, and Title Fees,               | RB 2X 360 004738 11 29 23  | Tead, which are known to the State of California to cause cancer and birth d<br>To minimize exposure, avoid breathing exhaust, do not idle the engine exce<br>vehicle in a well-ventilated area and wear gloves or wash your hands freque<br>For more information go to www.P65Warnings.ca.gov/passenger-vehicle.  |

