KAN-005344 _{TX}	4-REBILL,NB,205344,RA302 13	995 220240119 6654	ULC U W TX CERT CERT TRD RAMP BUMP	C 02 CAMP BOOK EXFL ROTA 4881
VEH	CLE DESCRIPTION F-150 2024 F-150 4X4 SUPERCREW 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO TRANS	S S S S S S S S S S S S S S S S S S S	RK D09937 K METALLIC CLOTH 40/CON/40 SEETY/SECURITY • ADVANCETRAC™ WITH RSC® • AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT • AIRBAGS - SAFETY CANOPY® • CTR HIGH MOUNT STOP LAMP • PERIMETER ALARM • SOS POST-CRASH ALERT SYS™ • STOLEN VEH SVCS: 1 YR PLAN • TIRE PRESSURE MONIT SYS • SYR/60,000 BUMPER / BUMPER • SYR/60,000 POWERTRAIN • SYR/60,000 POWERTRAIN • SYR/60,000 POWERTRAIN • SYR/60,000 HYBRID BATTERY MARTION • SS2,110.00 ONS/OTHER \$5,385.00 • A DELIVERY \$1,995.00 FORE DISCOUNTS \$7,380.00 • ADOMINER \$7,380.00	EPA DOT Fuel Economy Fuel Economy MPG Fuel Economy MPG Image: Standard Pic 3 MPG. Standard Pic 3 MPG. Image: Standard Pic 3 MPG. Image: Standard Pic 3 MPG.<
				Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★★★★★), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42
	CATB		MSRP \$55,380.00 Whether you decide to lease or finance your	1FTFW2L56RKD09937
	RAMP TWO		vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	oline, License, and Title Fees, luded. Dealer installed RA302 R	RB 2X 420 005344 01 30 24	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

2202401196654

