



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2024 F350 SRW 4X2 CREW CAB
XL 176" WB STYLESIDE
6.7 HI OUTPUT POWER STROKE
10-SPEED AUTO TORQSHIFT

RE C05106

EXTERIOR OXFORD WHITE
INTERIOR MEDIUM DARK SLATE VINYL

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- DOOR HANDLES - BLACK
- HEADLAMPS - AUTOLAMP (ON/OFF)
- TOW HOOKS
- TRAILER BRAKE CONTROLLER
- TRAILER SWAY CONTROL
- TRAILER TOW MIRRORS
- WIPERS- INTERMITTENT

INTERIOR

- 4.2" PRODUCTIVITY SCREEN
- AIR COND, MANUAL FRONT
- CLOTH SUN VISORS
- DRIVER SEAT-MANUAL LUMBAR
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- REAR VIEW CAMERA
- REMOTE KEYLESS ENTRY
- SYNC@4 W/8" SCREEN
- TWIN I-BEAM INDEPENDENT FRT SUSPENSION W/STAB BAR

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYS™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

- PREFERRED EQUIPMENT PKG.610A
- 6.7 HI OUTPUT POWER STROKE
- 10-SPEED AUTO TORQSHIFT
- LT245/75R17E BSW ALL-TERRAIN
- 3.31 RATIO REGULAR AXLE
- FRONT LICENSE PLATE BRACKET
- 11100# GVWR PACKAGE
- ENGINE BLOCK HEATER
- 50 STATE EMISSIONS
- PRO POWER ONBOARD - 2KW
- BLIS (BLIND SPOT INFO SYSTEM) JACK
- WHEEL WELL LINERS FRONT & REAR
- LED BOX LIGHTING
- HEAVY SERVICE FRONT SUSPENSION
- REVERSE SENSING SYSTEM
- REMOTE START SYSTEM
- TAILGATE STEP
- DUAL BATTERY
- 360-DEGREE CAMERA PACKAGE
- XL DRIVER ASSIST PACKAGE

(MSRP)

12,495.00
NO CHARGE
165.00
NO CHARGE
NO CHARGE
190.00
NO CHARGE
985.00
325.00
60.00
125.00
250.00
375.00
NO CHARGE
1,150.00
730.00

PRICE INFORMATION

BASE PRICE	\$50,015.00
TOTAL OPTIONS/OTHER	16,850.00
TOTAL VEHICLE & OPTIONS/OTHER	66,865.00
DESTINATION & DELIVERY	1,995.00

(MSRP)

RAMP ONE		TOTAL MSRP \$68,860.00
RK34		
RAMP TWO	RAIL	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance .
	ITEM #: 52-5010 O/T 1	

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

SPECIAL ORDER
RC142 N RB 2X 425 001662 03 14 24

California Air Resources Board

Diesel Vehicle

Environmental Performance

These ratings are not directly comparable to the U.S. EPA/DOT light-duty vehicle label ratings. For information on how to compare, please see www.arb.ca.gov/ep_label.

Protect the environment. Choose vehicles with **higher ratings**:

Greenhouse Gas Rating (tailpipe only)



Smog Rating (tailpipe only)



Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



The FordPass® Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977–2022 CY total sales.
**FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.



Insist on Ford Protect! The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit www.FordOwner.com.

1FT8W3AM3REC05106



WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

SCAN QR TEXT 1FRECO5106 TO 48028

Msg & Data rates may apply. Text HELP for help



www.ford.com/help/privacy-terms/