KAN-004614 _{TX}	9-NORMAL,NB,204614,RE302 832	220240606 1790	ULC U W TX CERT CERT TRD RAMP BUMP	C 02 CAMP BOOK EXFL ROTA 2483
VEHIC	CLE DESCRIPTION 5-150 2024 F-150 4X2 SUPERCREW 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	EXTERIOR AGATE BLACK INTERIOR BLACK STX CONTERIOR BLACK STX CONTERIOR BLIS W/CROSS-TRAFFIC ALERT CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECT OR CURVE CONTROL FORDPASS TM CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST LANE-KEEPING SYSTEM POST-COLLISION BRAKING PRE-COLLISION BRAKING PRE-COLLISION BRAKING PRE-COLLISION BRAKING PRE-COLLISION BRAKING SELECTSHIFT® SYNC®4 W/EVR & 12" SCREEN DASE PRICE TOTAL OPTIC	CERT CERT CERT TRD RAMP BUMP RK D95293 K METALLIC COTH 40/CON/40 SAPETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP PERIMETER ALARM SOS POST-CRASH ALERT SYS™ AIRB PRESSURE MONIT SYS DATA PRESSURE MONIT SYS MARRANTY AYR/36,000 POWERTRAIN SYR/60,000 POWERTRAIN AYR/100,000 HYBRID BATTERY	EPA Fuel Economy and Environment Fuel Economy Fuel Economy Particle Paricle Partic
6426# GVWR PACKAGE FRONT LICENSE PLATE BRACKET STX BLACK APPEARANCE PACKAGE .20" GLOSS BLACK WHEELS 50 STATE EMISSIONS	NO CHARGE 1,585.00 NO CHARGE		OUNT - 2,000.00	Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size a Frontal Driver Crash Passenger Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size a Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover $\bigstar \bigstar \bigstar$ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars ($\star \star \star \star$), with Source: National Highway Traffic Safety Administry WWW.safercar.gov or 1-888-327-42 IFTEW2KP2RKD95293
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inc	e Federal Automobile line, License, and Title Fees, Ided. Dealer installed RE302 N	RB 2X 445 004614 05 30 24	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

06/02/2024

