U W TX ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

	CLE DESCRIPTION EXPEDITION LIMITED 42 2024 EXPEDITION LIMITED 42 LIMITED 7-PASSENGER 3.5L ECOBOOST V6 ENGINE 10SPD AUTO TRANS W/SLCTS	K4 EXTERIOI ICONIC INTERIOR	C SILVER METALLIC	567	EPA DOT Fuel Economy and Er Fuel Economy MPG. The
STANDARD EQUIPMENT INDEDLETAT EXTERIOR • ACOUSTIC-LAMINATE WINDSHLD • ACTIVE GRILLE SHUTTERS • DOOR HANDLES - BODY COLOR W/BRIGHT INSERTS • EASY FUEL® CAPLESS FILLER • HEADLAMPS-LED REFLECTOR W/LED SIGNATURE LIGHTING • PANORAMIC VISTA ROOF® • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • ROOF-RACK SIDE RAILS-BRGHT TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 302A • RUNNING BOARDS, POWER DEPLOY • 22" 12-SPK POLISHED ALUM WHL OTTONAL EQUIPMENT/OTHER P285/45R22 A/S BSW TIRES HEAVY-DUTY TRAILER TOW PKG 2ND ROW CAPTAIN CHAIR SEATS ADV CARGO MAN W/BLK RR XBARS 15.5 LCD SCREEN W/TOUCH CAP FRONT LICENSE PLATE BRACKET	International and a second sec	BAS TOT TOT	N START AIRBAGS - DUAL ST AIRBAGS - SAFETY SPKR PAK PERIMETER ALARM PERIMETER ALARM SIST+ ODEM SECURICODE KEYL SECURILOCK® ANT M SOS POST-CRASH K&HI SYSTEM AIRBAGS - DUAL ST AIRBAGS - SAFETY PERIMETER ALARM SECURICODE KEYL SYSTEM	TAGE FRONT CANOPY® PACT TY SYSTEM ' SYSTEM™ ALERT ESS KEYPAD II-THEFT SYS ALERT SYS™ R / BUMPER TRAIN	index 16 22 inghway ity highway 5.6 gallons per 100 miles Annual fuel Costs 53,0000 Image: Control of the second s
	RAMP ONE RK34 RAMP TWO ITEM # This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	RAIL 52-0903 O/T 2 The Federal Automobile asoline, License, and Title Fees, acluded. Dealer installed	OTAL MSRP \$78, Whether you decide to leas vehicle, you'll find the choir d Credit for you. See your dealer for www.ford.com/finance.	ces that are right details or visit	IFMJU2A81REA31567 WARNING: Operating, servicing and maintaining a particular of the state of California to cause carr Vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause carr To minimize exposure, avoid breathing exhaust, do not idle to vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe

