MIC-003901 <sub>TX</sub>	9-NORMAL,NB,203901,RE022 894	8 320240509 5571	ULC     U     W     TX       CERT CERT CERT     TRD     RAMP BUMP (	CAMPBOOKEXFLROTA 0
	CLE DESCRIPTION BRONCO 2024 BLACK DIAMOND 4-DR 4X BLACK DIAMOND - 5 PASSENGE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	R OXFORD WHI INTERIOR		EPA DOT Fuel Economy and Env Fuel Economy MPG Small SUVs The best ver
STANDARD EQUIPMENT INCLUDED A EXTERIOR • BUMPER,REAR-PWDR CTD STEEL • EASY FUEL® CAPLESS FILLER • FENDER TIE-DOWN HOOKS • FULL VEH STEEL BASH PLATES • GRILLE-BLK MIC/BRONCO WHTE • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LED • MIRRORS-HTD/POWER GLASS, MANUAL FOLD/SPOTTER MIRROR • TOW HOOKS-FRT (2)/REAR (1)	AT NO EXTRA CHARGE INTERIOR • 1TOUCH UP/DOWN DR/PASS WIN • 6-WAY MANUAL DRV/PASS SEAT • 60/40 SPLIT FOLD REAR SEAT • AUX SWITCHES W/PRE-WIRING • CRUISE CONTROL • IP CLUSTER 8" DIGITAL SCRN • LOCKING GLOVE BOX • LTHR GEAR KNOB/STR WHEEL • MANUAL A/C, SINGLE ZONE • MARINE GRADE VINYL SEATS • MOLLE STRAP SYSTEM • POWERPOINTS - 12V • RUBBERIZED FLOOR, WASHOUT CAPABLE W/DRAIN PLUG • SMART CHARGING USB PORTS	EUNCTIONAL • 12"LCD CTR STACK TOUCHSCRN • AUTO START STOP TECH • BRAKES, 4-WHEEL DISC/ABS • FORDPASS™ CONNECT • FRONT STABILIZER BAR • HILL START ASSIST • PRE-COLLISION ASSIST W/AEB • PUSH-BUTTON START • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SIRIUSXM® W/360L- NA AK&HI • SYNC®4 • TER MGMT W/G.O.A.T. MODES® • TOOL KIT- DOOR/TOP REMOVAL	SAFETY/SECURITY • ADVANCETRAC <sup>™</sup> WITH RSC® • AIRBAGS-FRNT (DUAL STAGE) & SIDE IMPACT/SAFETY CANOPY® SYSTEM (ALL ROWS) • BELT-MINDER CHIME • CHILD SAFETY REAR DR LOCKS • ELCTR STABILITY/TRACTN CTL • INDIV TIRE PRESS MONIT SYS • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • PERSONAL SAFETY SYSTEM <sup>™</sup> SYR/36,000 BUMPER / BUMPER • SYR/60,000 POWERTRAIN • SYR/60,000 ROADSIDE ASSIST	Long the second
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 321A •BLACK DIAMOND SERIES OPTIONAL EQUIPMENT/OTHER 10-SPEED AUTO TRANSMISSION LT265/70R17 A/T TIRES (32") 4.46/REAR AXLE-LOCKING DIFF FRONT AXLE-OPEN DIFFRNTL ROCK RAILS STEEL FRONT BUMPER AM/FM,7 SPKRS,SDARS 17" BLK GLOSS-PNTD ALUM WHLS HARD TOP,GRAY MOLDED-IN-COLOR .SOUND DEADENING HEADLINER .FRT ROW TOP PANEL STORAGE BAG FRONT LICENSE PLATE BRACKET	(MSRP) 1,495.00 2,190.00 NO CHARGE		\$44,070.00           DNS/OTHER         3,685.00           CLE & OPTIONS/OTHER         47,755.00	<b>Example 1 Example 2</b> Calculate personalized estimates and compare vehicles <b>COVERNMENT 5-STAR SAFETY Overall Vehicle Score Not Rat</b> Based on the combined ratings of frontal, side and rollover.         Should ONLY be compared to other vehicles of similar size at <b>Frontal</b> Driver <b>Crash</b> Passenger         Based on the risk of injury in a frontal impact.         Should ONLY be compared to other vehicles of similar size at <b>Side</b> Front seat <b>Crash</b> Rear seat         Based on the risk of injury in a side impact.         Based on the risk of injury in a side impact. <b>Based on the risk of injury in a side impact</b> Based on the risk of injury in a side impact.         Based on the risk of injury in a side impact.         Based on the risk of injury in a side impact.         Based on the risk of injury in a side impact.         Based on the risk of injury in a side impact.         Based on the risk of rollover in a single-vehicle crash.
	RAMP ONE RPTB RAMP TWO ITEM #: 5 This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not inclu options or accessories are not inclu	RAIL 2-8697 O/T 2 Ford Credit e Federal Automobile ine, License, and Title Fees, ded. Dealer installed	MSRP \$49,650.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. RB 2X 435 003901 05 02 24	IFMDE1BH1RLA57407 WARNING: Operating, servicing and maintaining a pas vehicle can expose you to chemicals including engine end lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passenge

3202405095571

05/15/2024

