KTP-000515 CA	4-REBILL,NB,200515,PM282 57	·		RT TRD RAMP BUMP C.	AMP BOOK EXFL ROTA 515/
	E DESCRIPTION UPER DUT 2024 F350 SRW 4X4 SUPERCA XL 164" WB STYLESIDE 6.7L POWER STROKE V8 DIESE 10-SPEED AUTO TORQSHIFT	B EXTERIOF OXFOR L INTERIOR	R D WHITE	52556	California Air Resources Board Environment These ratings are not directly comparable to
LT245/75R17E BSW ALL-TERRAIN 3.31 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 11300# GVWR PACKAGE	IVERIAL CHARGE INTERION 4.2" PRODUCTIVITY SCREEN 4.2" PRODUCTIVITY SCREEN CLOTH SUN VISORS DRIVER SEAT-MANUAL LUMBAR OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING: TILT/TELESCOPE, CRUISE & AUDIO CONTROLS (MSRP) 9,995.00 NO CHARGE 165.00 430.00 NO CHARGE 165.00 NO CHARGE 165.00 NO CHARGE 165.00 NO CHARGE 165.00 NO CHARGE 225.00	BASI TOT/ TOT/	WI-FI DEM • BELT-MINDE • DRIVER/PAS • SECURILOCH • SOS POST-C WARRANTY • 3YR/36,000 E • 5YR/60,000 F	AC [™] WITH RSC® AFETY CANOPY® R CHIME SENGER AIR BAGS (® ANTI-THEFT SYS RASH ALERT SYS™ BUMPER / BUMPER POWERTRAIN ROADSIDE ASSIST DIESEL ENGINE (MSRP) \$51,345.00 12,155.00	For information on how to compar Protect the environment. Cho Greenhouse Gas Rating (tailpipe only C A+ Cleaner Vehicle emissions are a primary contributor to climate California Air Resources Board based on this vehicle?
	RAMP ONE RA84 RAMP TWO ITEM #:	RAIL	Whether you decide	565,495.00 to lease or finance your he choices that are right aler for details or visit	IFT8X3BT1REC52556 WARNING: Operating, servicing and maintaining a passen vehicle can expose you to chemicals including engine exha
	This label is affixed pursuant to t Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	ne Federal Automobile Iline, License, and Title Fees, uded. Dealer installed	WWW.ford.com/fina SPECIAL O 1282 R RB X 420 0005	RDER	Vehicle can expose you to chemicals including engine exha lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the en- vehicle in a well-ventilated area and wear gloves or wash your har For more information go to www.P65Warnings.ca.gov/passenger-v

