
OHI-000143 PA 16C 422 6B	2XADJCOVPRCSB10RAMPBUMP	1FDWE3FN6SDD15313	E-SERIES	MAIL	023443 273/462	
DRW 158" 7.3L V8 PF	RIES	SD D1	5313		nomy and Environ	
HEADLAMPS - AUTOLAMP (ON/OFF) INTERVAL WIPERS BLACK VINYL GLOVE BOX W POWERPOINT	PNING • AUX TRANSMISSION 0 W/ BLUETOOTH® • BATTERY - 78 AMP- FLOOR COVERING • FLEET TELEMATICS V/ 12V PWR PT • HILL START ASSIST - 12V (FRONT) • TWIN I-BEAM INDEP ILT/TELESCOPIC FRONT SUSPENSION R • HEADLINER	HR • 4-WHEEL ANTI-I BRAKING SYSTE • DRIVER/PASSEN • TRACTION CON WARRANTY	Y BELTS LOCK DISC EM NGER AIR BAGS ITROL IPER TO BUMPER WERTRAIN ADSIDE ASSIST (MSRP) \$38,295.00 3,620.00	REQUIRED ON T		
4.56 LIMITED SLIP AXLE XF5 270.00 HIGH-SERIES EXT UPGRADE PKG 100.00 POWER EQUIPMENT GROUP 600.00 RAW MATERIALS SURCHARGE NO CHARGE FRONT LICENSE PLATE BRACKET NO CHARGE REVERSE GEAR ALARM 125.00 12500# GVWR PACKAGE 350.00 NO CHARGE 85.00 DRIVER ASSIST TECH PACKAGE 1,365.00 MIRRORS,MAN TLR TOW W/PWR GLS 230.00 INSTRUMENT PANEL ELEC MESSAGE NO CHARGE REMOTE KEYLESS ENT/PANIC ALARM NO CHARGE		DESTINATION & DELIVERY				
	CG07 CONVOY ITEM #: 16-5028 O/T 59 16-5028 O/T 59	TOTAL MSRP\$4Image: State of the state of	choices that are right er for details or visit		1FDWE3FN6SDD15313 servicing and maintaining a passenger vehic to chemicals including engine exhaust, carbut tate of California to cause cancer and birth d	
Info Sta	is label is affixed pursuant to the Federal Automobile ormation Disclosure Act. Gasoline, License, and Title Fees, ate and Local taxes are not included. Dealer installed tions or accessories are not included unless listed above.	SPECIAL OR	SPECIAL ORDER R 6B 2X 515 000143 05 01 24		lead, which are known to the State of California to cause cancer and birth d To minimize exposure, avoid breathing exhaust, do not idle the engine exce vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.	

06/01/2024



www.ford.com/help/privacy-terms/