СНІ-004196 тх	9-NORMAL,NB,104196,RC061 267	72 120240316 5561	UTCUWTXCERTCERTCERTTRDRAMPBUMPC	CAMP BOOK EXFL ROTA 2194/2254
	CLE DESCRIPTION EXPLORER XLT RWD 2024 EXPLORER XLT RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	RG A56358 O GRAY METALLIC LATE ACTIVEX SEAT	Fuel Economy and Environ Fuel Economy MPG. The best vehicle of MPG. The best vehicle of MPG. The best vehicle of MPG.
 STANDAND EQUIPMENT INCLODED A EXTERIOR DOOR HANDLES - BODY COLOR EASY FUEL® CAPLESS FILLER HEADLAMPS - AUTO LED LED SIGNATURE LIGHTING MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS POWER LIFTGATE PRIVACY GLASS - REAR DOORS REAR INT WIPER/WASH/DFRST REAR SPOILER, BODY COLOR ROOF-RACK SIDE RAILS-BLACK TAILEA SWAY CONTROL VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 2020 . REMOTE START SYSTEM . HEATED STEERING WHEEL . AWAY POWER PASSENGER SEAT . DYNONE PASSENGER SEAT . DYNONE PASSENGER SEAT . STATE EMISSIONS CLASS IV TRAILER TOW PACKAGE . AGI TE WI-FI HOTSPOT CREDIT XLT SPORT APPEARANCE PACKAGE . 20" CRBN GRAY-PTD 10-SPK WHLS . FRONT LICENSE PLATE BRACKET	International and a state of the second state		\$38,670.00	Image: State of the second state second state of the se
	RAMP ONE	ΤΟΤΑΙ	. MSRP \$46,325.00	www.safercar.gov or 1-888-327-4236 1FMSK7DH8RGA56358
	RAMP TWO	CONVOY 52-975W O/T 2 Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passenger vehicl vehicle can expose you to chemicals including engine exhaust, carbo lead, which are known to the State of California to cause cancer and birth d
This label is affixed pursuant to the Federal Automo Information Disclosure Act. Gasoline, License, and State and Local taxes are not included. Dealer insta options or accessories are not included unless list		line, License, and Title Fees, uded. Dealer installed RC061 N	, RC061 N RB 2X 425 004196 03 06 24	To minimize exposure, avoid breathing exhaust, do not idle the engine excersion vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202403165561

06/03/2024

