	LABL ADJ COV P	K B10 RAMP BUMP	1FDWE3FN7SDD09682	E-SERIES	MAIL	0 41
	CLE DESCRIPTION E-SERIES 2025 E-350 CUTAWAY SR SRW 158 WB 7.3L V8 PREMIUM-RATED ELEC 6-SPD AOD W/TOW) ENG. INTE	SD ERIOR XFORD WHITE ERIOR MEDIUM FLINT VINYL	09682		onomy and En
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (NOOFF) • INTERVAL WIPERS • LT245/75R16E BSW A/S TIRES • SOLAR TINTED GLASS INCLUDED ON THIS VEHICLE MERERED EQUIPMENT PKG.780A STANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. 4.10 LIMITED SLIP AXLE XE6 POWER EQUIPMENT GROUP RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 1050# GWWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL MINTED SLIP ATLE DENG. 1050# GWWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL MINTED SLIP ATLE TOW W/PWR GLS 16/7 WHITE PAINTED STEEL WHLS 17MS REMOTE KEYLESS ENT/PANIC ALARM	IND EXTRA CHARGE AIR CONDITIONING AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING GLOVE BOX W/ 12V PWR PT POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER VINYL FRONT HEADLINER VINYL SUN VISORS (MSRP) NO CHARGE 270.00 100.00 600.00 NO CHARGE NO CHARGE		I COOLER HR MODEM ENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT N SENDENT SEN	000 BUMPER TO BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST (MSRP) \$38,045.00 1,465.00 %OTHER 39,510.00 1,995.00 CE USE. VOID IF	fuelecono	DUIRED O
	RAMP ONE CE07	00111/01/		\$41,505.00		1FDWE3FN7SDD09682
	RAMP TWO CONVOY ITEM #: 11-0286 O/T 59 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance. SPECIAL ORDER R924 R 6B 2X 515 000240 04 26 24		WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause canc To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng	

06/01/2024

