MIC-007071 _{TX}	9-NORMAL,NB,107071,RE221 872		ULC U W TX CERT CERT CERT TRD RAMP BUMP C	CAMP BOOK EXFL ROTA 433
	CLE DESCRIPTION BRONCO 2024 OUTER BANKS 4-DOOR 4X OUTER BANKS - 5 PASSENGER 2.7L ECOBOOST V6 ENGINE 10-SPEED AUTO TRANSMISSION	CACTUS GRAY	RL A50807	EPA DOT Fuel Economy and Env Fuel Economy MPG Small SUVs The best ve
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • EASY FUEL® CAPLESS FILLER • FENDER TIE-DOWN HOOKS • GRILLE-BLK/BRONCO WHITE • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LED • TOW HOOKS-FRT (2)/REAR (1)	IND EXTRA CHARGE INTERIOR • 1TOUCH UP/DOWN DR/PASS WIN • 60/40 SPLIT FOLD REAR SEAT • A/C, DUAL ZONE CLIMATE CTL • CARPET FLOORING, BOTH ROWS • IP CLUSTER 8" DIGITAL SCRN • LEATHER-TRIM/VINYL SEATS • LOCKING GLOVE BOX • LTHR GEAR KNOB/STR WHEEL • POWERPOINTS - 12V • PWR 10-WAY DRV/8-WAY PASS • SMART CHARGING USB PORTS • TILT/TELESCOPE STR COLUMN	EUNCTIONAL • 12"LCD CTR STACK TOUCHSCRN • AUTO START STOP TECH • BRAKES, 4-WHEEL DISC/ABS • FORD CO-PILOT360™ • FORDPASS™ CONNECT • FRONT STABILIZER BAR • HILL START ASSIST • MID PACKAGE • PUSH-BUTTON START • SIRIUSXM® W/360L- NA AK&HI • SYNC®4 W/EVR • TER MGMT W/G.O.A.T. MODES® • TOOL KIT- DOOR/TOP REMOVAL	SAFETY/SECURITY • ADVANCETRAC™ WITH RSC® • AIRBAGS-FRNT (DUAL STAGE) & SIDE IMPACT/SAFETY CANOPY® SYSTEM (ALL ROWS) • BELT-MINDER CHIME • CHILD SAFETY REAR DR LOCKS • ELCTR STABILITY/TRACTN CTL • INDIV TIRE PRESS MONIT SYS • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • PERSONAL SAFETY SYSTEM [™] MARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 ROADSIDE ASSIST	tin the series of the series o
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 314A •OUTER BANKS SERIES •HIGH/LUX PACKAGE •360-DEGREE CAMERA •ADAPTIVE CRUISE CONTROL •HEATED STEERING WHEEL •WIRELESS CHARGING PAD OPTIONAL EQUIPMENT/OTHER 2024 MODEL YEAR CACTUS GRAY 2.7L ECOBOOST V6 ENGINE AM/FM,10 SPKRS,SDARS CNCTD NAV (1-YEAR SUB INC) SASQUATCH PACKAGE .ADVANCED 4X4 .17"BLK ALM BEADLCK ALLOY RING 4.7/REAR AXLE-LOCKING DIFF .FRONT AXLE-LOCKING DIFF .FRONT AXLE-LOCKING DIFF .FRONT AXLE-LOCKING DIFF .FRONT AXLE-LOCKING DIFF .FRONT AXLE-LOCKING DIFFRNTL .LT315/70R17 M/T TIRES (35") HARD TOP,GRAY MOLDED-IN-COLOR .SOUND DEADENING HEADLINER .FRT ROW TOP PANEL STORAGE BAG FRONT LICENSE PLATE BRACKET AUXILIARY SWITCHES DEALER INSTALLED OPTIONS Wheel Lock Kit Trailer Tow Package	(MSRP) 2,930.00 2,95.00 2,145.00 7,460.00 2,190.00 2,190.00 100.00 500.00		\$47,940.00 NS/OTHER 15,815.00 LE & OPTIONS/OTHER 63,755.00	emissions are a significant cause of climate change and smog. fueleconogy Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Not Ra Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size a Frontal Driver Crash Passenger Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size a Side Front seat Rear seat Not Ra Based on the risk of injury in a side impact. Should ONLY be compared to other vehicles of similar size a Side Front seat Rear seat Not Ra Based on the risk of injury in a side impact. Based on the risk of injury in a side impact. Based on the risk of rollover in a single-vehicle crash. Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (*****), wi Source: National Highway Traffic Safety Admini
	RAMP ONE RH80 RAMP TWO ITEM #: 5 This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inclu	RAIL 52-3696 O/T 2 e Federal Automobile line, License, and Title Fees, ided. Dealer installed	MSRP \$65,650.00 Whether you decide to lease or finance your rehicle, you'll find the choices that are right or you. See your dealer for details or visit www.ford.com/finance.	www.safercar.gov or 1-888-327-4 IFMEE8BP9RLA50807 WARNING: Operating, servicing and maintaining a pas vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

3202405300781

06/03/2024

