KAN-003657 <sub>TX</sub>	9-NORMAL,NB,203657,RE142 <b>104</b>	105 220240522 6643 BLEND 6643	ULC U W TX   CERT CERT CERT TRD RAMP BUMP OF	C 02 CAMP BOOK EXFL ROTA 2284
VEHIC	CLE DESCRIPTION <b>F-150</b> 2024 F-150 4X2 SUPERCREW 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	ELEND CONTO EXTERIOR ATLAS BLUE I INTERIOR BLACK STX C EUNCTIONAL • AM/FM STEREO • BLIS W/CROSS-TRAFFIC ALERT • CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECTOR • CURVE CONTROL • FORDPASS <sup>™</sup> CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM • HILL START ASSIST • LANE-KEEPING SYSTEM • POST-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION BRAKING • SELECTSHIFT® • SYNC®4 W/EVR & 12" SCREEN • DASE PRICE TOTAL OPTION	RK E288842     METALLIC     LOTH 40/CON/40     SEETY/SECURITY     • ADVANCETRAC™ WITH RSC®     • AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT     • AIRBAGS - SAFETY CANOPY®     • CTR HIGH MOUNT STOP LAMP     • PERIMETER ALARM     • SOS POST-CRASH ALERT SYS™     • TIRE PRESSURE MONIT SYS     • TIRE PRESSURE MONIT SYS     • SYR/60,000 BUMPER / BUMPER     • SYR/60,000 ROADSIDE ASSIST     • SYR/60,000 HYBRID BATTERY     • SYR/100,000 HYBRID BATTERY     • SYR/00,000 HYBRID BATTERY <td>AMP BOOK EXFL ROTA 2284 CAMP BOOK EXFL ROTA 2284 CONSTRUCTION CONST</td>	AMP BOOK EXFL ROTA 2284 CAMP BOOK EXFL ROTA 2284 CONSTRUCTION CONST
	RAMP ONE	TOTAL	MSRP \$48,225.00	Based on the risk of injury in a side impact.     Rollover   ★ ★ ★     Based on the risk of rollover in a single-vehicle crash.     Star ratings range from 1 to 5 stars (★ ★ ★ ★ ), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42     IFTEW2KPORKE28842
	CATB   RAMP TWO	CONVOY	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to th Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	ne Federal Automobile Jline, License, and Title Fees, uded. Dealer installed <b>BE142 N</b>	RB 2X 440 003657 05 14 24	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

