
VEH	ICLE DESCRIPTION		^{sк} А81	101	California Air Resources Board
ford.com	2025 350 MR PASS XL TRIM 3.5L ECOBOOST V6 10-SPEED TRANSMI	(GAS) INTE	ERIOR DXFORD WHITE ERIOR DARK PALAZZO GRAY CLOTH		Environmental
STANDARD EQUIPMENT INCLUDED					These ratings are not directly comparable to the U
EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL	INTERIOR • AIR CONDITIONING • ASSIST HANDLE - B-PILLA • ASSIST HANDLES - A-PILL • CENTER CONSOLE	AR • ELECTRONIC PWR A AR • FORDPASS™ CONN	NCTIONALSAFETY/SECURITYUTO HIGH-BEAM HEADLAMPS LECTRONIC PWR ASST STEER• 3 POINT SAFETY BELTS • ADVANCETRAC™ WITH RSC® • AIRBAGS ⊠ FRONT, SIDE AND SAFETY CANOPY® SYSTEM		For information on how to compare, plea Protect the environment. Choose
• WIPERS - RAIN-SENSING	POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER POST-COL PRE-COLL		EPING SYSTEM SOS POST-CRASH ALERT SYS™ • TIRE PRESSURE MONIT SYS LISION ASSIST W/AEB		Greenhouse Gas Rating (tailpipe only)
		• REAR VIEW CAMER W/ TRAILER HITCH A • SELECTABLE DRIVE • USB PORTS - 5 AMF	ASSIST • 3YR/36,000 BUMPER MODES • 5YR/60,000 POWER	TRAIN	A+ D Cleaner
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	Vehicle emissions are a primary contributor to climate chan California Air Resources Board based on this vehicle's meas
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.301A			PRICE INFORMATION BASE PRICE TOTAL OPTIONS/OTHER	\$57,700.00 9,430.00	
3.5L ECOBOOST V6 (GAS) 3.73 NON-LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET 9500# GVWR PACKAGE	2,700.00 NO CHARGE NO CHARGE NO CHARGE	ford	TOTAL VEHICLE & OPTIONS/OTHER DESTINATION & DELIVERY	67,130.00 2,095.00	GOVERNMENT 5-STAR SAFETY RATIN
50 STATE EMISSIONS REVERSE SENSING SYSTEM KEYLESS ENTRY PAD	NO CHARGE NO CHARGE 95.00				Overall Vehicle Score $\bigstar \bigstar \bigstar \bigstar$ Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and weight.
HD TRAILER TOW PACKAGE FRONT FOG LAMPS ELEC AIR TEMP CONTROL	485.00 NO CHARGE NO CHARGE				
SYNC 4 HD BLUETOOTH VEHICLE MAINTENANCE MONITOR 360-DEGREE CAMERA LANE KEEPING SYSTEM	1,165.00 45.00 1,000.00 795.00				FrontalDriver★ ★ ★ ★CrashPassenger★ ★Based on the risk of injury in a frontal impact
BLIND SPOT ASSIST 1.0 EXTENDED FUEL TANK (31 GAL) FRONT OVERHEAD SHELF	NO CHARGE 285.00 75.00				Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and weight. Side Front seat $\star \star \star \star \star \star$
TRAILER BRAKE CONTROLLER LARGE CENTER CONSOLE RUNNING BOARD 2 ADDITIONAL KEYS	405.00 NO CHARGE 310.00 75.00				SideFront seatCrashRear seatBased on the risk of injury in a side impact.
PRIVACY GLASS 15-PASSENGER SEATS	500.00 1,495.00				Rollover $\bigstar \bigstar$ Based on the risk of rollover in a single-vehicle crash.
					Star ratings range from 1 to 5 stars (★★★★), with 5 being Source: National Highway Traffic Safety Administration (N www.safercar.gov or 1-888-327-4236
	RAMP ONE		TOTAL MSRP \$69,	225.00	1FBAX2CG2SKA81101
	RAMP TWO	CONVOY	Scan The QR Code to		
		ITEM #: 71-F010 O/T 2	get more details about this vehicle		WARNING: Operating, servicing and maintaining a passenger vehic vehicle can expose you to chemicals including engine exhaust, carb lead, which are known to the State of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state of California to cause cancer and birth of the state
	Information Discl State and Local ta	ed pursuant to the Federal Automobile osure Act. Gasoline, License, and Title Fees, ixes are not included. Dealer installed ories are not included unless listed above.	SE282 N RB 2X 530 004564 05	28 25	To minimize exposure, avoid breathing exhaust, do not idle the engine exc vehicle in a well-ventilated area and wear gloves or wash your hands frequ For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202506067754



www.ford.com/finance