| KAN-000289 <sub>NC</sub>  | 9-NORMAL,NB,200289,RM102 <b>107</b>  | 791 120241218 6023  | ULC     U     W       CERT CERT CERT     TRD     RAMP BUMP C  | CAMPBOOKEXFLROTA 02<br>349/  |
|---|--|---|---|--|
|   | CLE DESCRIPTION<br>TRANSIT<br>2024 350 LR PASS XLT RWD<br>XLT TRIM   | EXTERIOR<br>OXFORD WH   | RK <b>B85035</b>  | California Air Resources Board   |
| ford.com  | 3.5L PFDI V6 (GAS)<br>10-SPEED TRANSMISSION  | INTERIOR  | ZO GRAY CLOTH   | Environmen   |
| STANDARD EQUIPMENT INCLUDED A   |  |   |   | These ratings are not directly comparable<br>For information on how to comp  |
| EXTERIOR<br>• AUXILIARY FUEL PORT<br>• BODY SIDE MOLDINGS - BLACK<br>• BUMPERS- BODY COLOR<br>• FOG LAMPS   | INTERIOR<br>• AIR CONDITIONING<br>• ASSIST HANDLES - A-PILLAR<br>• ASSIST HANDLE - B-PILLAR<br>• CENTER CONSOLE W/STORAGE  | FUNCTIONAL<br>• BLIND SPOT ASSIST<br>• ELECTRONIC PWR ASST STEER<br>• FORD CO-PILOT360™<br>• FORDPASS™ CONNECT 4GWI-FI              | SAFETY/SECURITY<br>• 3 POINT SAFETY BELTS<br>• ADVANCETRAC <sup>™</sup> WITH RSC®<br>• AIRBAGS ⊠ FRONT, SIDE AND<br>SAFETY CANOPY® SYSTEM       | Protect the environment. Ch  |
| <ul> <li>FULL SIZE SPARE TIRE/WHEEL</li> <li>FULL SIZE SPARE TIRE/WHEEL</li> <li>HEADLAMP COURTESY DELAY</li> <li>HEADLAMPS -<br/>AUTOMATIC</li> <li>WIPERS - RAIN-SENSING</li> </ul>   | CRUISE CONTROL     ILLUMINATED SUN VISORS     LOCKING GLOVE BOX     POWERPOINT - 12V (FRONT)     STEERING - TILT/TELESCOPIC  | HOTSPOT TELEMATICS MODEM<br>• LANE KEEPING SYSTEM<br>• POST-COLLISION BRAKING<br>• PRE-COLLISION ASSIST W/AEB<br>• REAR VIEW CAMERA | BRAKES - 4WHEEL DISC W/ABS     SECURILOCK® ANTI-THEFT SYS     SOS POST-CRASH ALERT SYS™     TIRE PRESSURE MONIT SYS                             | Greenhouse Gas Rating (tailpipe or   |
|   | WHEEL WITH AUDIO   | W/ TRAILER HITCH ASSIST<br>• SYNC®4 W/EVR & 12" SCREEN<br>• USB PORTS - 5 AMP   | WARRANTY<br>• 3YR/36,000 BUMPER / BUMPER<br>• 5YR/60,000 POWERTRAIN<br>• 5YR/60,000 ROADSIDE ASSIST   | A+ D<br>Cleaner<br>Using alternative   |
| INCLUDED ON THIS VEHICLE  | (MSRP)   |   | (MSRP)  | Vehicle emissions are a primary contributor to clim<br>California Air Resources Board based on this vehicl   |
| OPTIONAL EQUIPMENT/OTHER<br>PREFERRED EQUIPMENT PKG.302A<br>3.73 NON-LIMITED SLIP AXLE<br>FRONT LICENSE PLATE BRACKET<br>180 DEGREE OPENING<br>9400# GVWR PACKAGE<br>50 STATE EMISSIONS<br>KEYLESS ENTRY PAD<br>ELEC AIR TEMP CONTROL<br>RUNNING BOARD<br>2 ADDITIONAL KEYS<br>HALOGEN HEADLAMPS<br>PRIVACY GLASS<br>15-PASSENGER SEATS<br>E-85 FLEX FUEL CAPABLE | NO CHARGE  | PRICE INFO<br>BASE PRICE<br>TOTAL OPTI  | \$56,585.00   |  |
|   |  |   | TOTAL VEHICLE & OPTIONS/OTHER     58,985.00       DESTINATION & DELIVERY     2,095.00   | GOVERNMENT 5-STAR SAFETY         Overall Vehicle Score       ★ ★ ★         Based on the combined ratings of frontal, side and rollover.         Should ONLY be compared to other vehicles of similar size ar   |
|   |  |   |   | Frontal<br>CrashDriver<br>Passenger* *Based on the risk of injury in a frontal impact.<br>Should ONLY be compared to other vehicles of similar size ar   |
|   |  |   |   | SideFront seatCrashRear seatBased on the risk of injury in a side impact.  |
|   |  |   |   | Rollover $\bigstar \bigstar$<br>Based on the risk of rollover in a single-vehicle crash.   |
|   |  |   |   | Star ratings range from 1 to 5 stars (★★★★), wit<br>Source: National Highway Traffic Safety Adminis<br>www.safercar.gov or 1-888-327-42  |
|   | RAMP ONE<br>CV32   | ΤΟΤΑΙ   | . MSRP \$61,080.00  | 1FBAX2Y84RKB85035  |
|   | RAMP TWO   | CONVOY<br>21-100X O/T 2 Ford Credit   | Whether you decide to lease or finance your<br>vehicle, you'll find the choices that are right<br>for you. See your dealer for details or visit | WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer  |
|   | This label is affixed pursuant to the Information Disclosure Act. Gase State and Local taxes are not include options or accessories are not include the Information options or a | he Federal Automobile<br>oline, License, and Title Fees,<br>luded. Dealer installed RM102 N   | www.ford.com/finance.<br>RB 2X 450 000289 12 10 24  | lead, which are known to the State of California to cause cancer<br>To minimize exposure, avoid breathing exhaust, do not idle the<br>vehicle in a well-ventilated area and wear gloves or wash your h<br>For more information go to www.P65Warnings.ca.gov/passenge |

## 

