ford.com

E-SERIES

2023 E-450 STRIPPED DRW DRW 158" WHEELBASE 7.3L V8 ECONOMY-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL**

PD **D**08612

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- AUXILIARY FUEL PORT
- LT225/75R16E BSW TIRES
- WIPERS- INTERMITTENT

<u>INTERIOR</u>

• STEERING - TILT/TELESCOPIC

• BATTERY - 78 AMP-HR • FLEET TELEMATICS MODEM

INTERIOR LESS TRIM

FUNCTIONAL

- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL TRACTION CONTROL

WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

4003-384P01/01/22 LF030 PREFERRED EQUIPMENT PKG.790A 7.3L V8 ECONOMY-RATED ENG. .4.56 RATIO REGULAR AXLE X83 RAW MATERIALS SURCHARGE 14000# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL AIR CONDITIONING, PREP

- 350.00

(MSRP)

NO CHARGE NO CHARGE NO CHARGE 240.00 400.00

PRICE INFORMATION

BASE PRICE TOTAL OPTIONS/OTHER

TOTAL VEHICLE & OPTIONS/OTHER DESTINATION & DELIVERY

> NOT FOR AMBULANCE USE. FORD WARRANTY IS VOID IF **USED AS AN AMBULANCE**

(MSRP)

\$33,315.00

33,605.00 1,295.00

290.00

EPA Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

fueleconomy.gov











CE07

RAMP TWO

CONVOY ITEM #:

47-F475 O/T 5C

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

TOTAL MSRP



Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

\$34,900.00

SPECIAL ORDER

NE091 N RB 2X 315 000104 05 09 22

1FC3E4KK3PDD08612

warning: Operating, servicing and maintaining a passenger vehicle, process, servicing to cause cancer and birth defects or other reports. lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



