

## **E-SERIES**

2023 E-450 STRIPPED DRW DRW 158" WHEELBASE 7.3L V8 ECONOMY-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL** 

## PD **D08614**

### **EXTERIOR**

- WIPERS- INTERMITTENT

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

- AUXILIARY FUEL PORT LT225/75R16E BSW TIRES

## **INTERIOR**

• STEERING - TILT/TELESCOPIC

- BATTERY 78 AMP-HR • FLEET TELEMATICS MODEM

**INTERIOR LESS TRIM** 

HILL START ASSIST

**FUNCTIONAL** 

• TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

### SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL
- TRACTION CONTROL

### WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

### **INCLUDED ON THIS VEHICLE**

### **OPTIONAL EQUIPMENT/OTHER**

4003-384P01/01/22 LF030 PREFERRED EQUIPMENT PKG.790A 7.3L V8 ECONOMY-RATED ENG. .4.56 RATIO REGULAR AXLE X83 RAW MATERIALS SURCHARGE 14000# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL AIR CONDITIONING, PREP

(MSRP)

- 350.00

**NO CHARGE** NO CHARGE NO CHARGE 240.00 400.00

## **PRICE INFORMATION**

BASE PRICE TOTAL OPTIONS/OTHER

**TOTAL VEHICLE & OPTIONS/OTHER** 

**DESTINATION & DELIVERY** 

## (MSRP)

\$33,315.00 290.00

> 33,605.00 1,295.00

NOT FOR AMBULANCE USE. FORD WARRANTY IS VOID IF **USED AS AN AMBULANCE** 

## EPA Fuel Economy and Environment

## **FUEL ECONOMY RATINGS NOT** REQUIRED ON THIS VEHICLE

## fueleconomy.gov Calculate personalized estimates and compare vehicles









## **CE07**

RAMP TWO

ITEM #:

options or accessories are not included unless listed above.

47-F477 O/T 5C

CONVOY

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed

## TOTAL MSRP



Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

\$34,900.00

## **SPECIAL ORDER**

NE101 N RB 2X 315 000111 05 10 22

# 1FC3E4KK7PDD08614

warning: Operating, servicing and maintaining a passenger vehicle, process, servicing to cause cancer and birth defects or other reports. lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



