

Go Further

ford.com

VEHICLE DESCRIPTION

E-SERIES

2023 E-450 STRIPPED DRW
DRW 176 WB
7.3L V8 ECONOMY-RATED ENG.
ELEC 6-SPD AOD W/TOW-HAUL

EXTERIOR

INTERIOR
LESS TRIM

PD D04385

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- AUXILIARY FUEL PORT
- LT225/75R16E BSW TIRES
- WIPERS- INTERMITTENT

INTERIOR

- STEERING - TILT/TELESCOPIC

FUNCTIONAL

- BATTERY - 78 AMP-HR
- FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL
- TRACTION CONTROL

WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

BUILT

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.790A
7.3L V8 ECONOMY-RATED ENG.
4.56 LIMITED SLIP AXLE XF3
RAW MATERIALS SURCHARGE
14000# GVWR PACKAGE
50 STATE EMISSIONS
AIR CONDITIONING, PREP
FRONT MAX GAWR

(MSRP)

- 350.00

270.00

NO CHARGE

NO CHARGE

NO CHARGE

400.00

40.00

PRICE INFORMATION

BASE PRICE

\$33,815.00

TOTAL OPTIONS/OTHER

360.00

TOTAL VEHICLE & OPTIONS/OTHER

34,175.00

DESTINATION & DELIVERY

1,295.00

NOT FOR AMBULANCE USE.
FORD WARRANTY IS VOID IF
USED AS AN AMBULANCE

BUILT

TOUGH

EPA
DOT

Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT
REQUIRED ON THIS VEHICLE

fueleconomy.gov

Calculate personalized estimates and compare vehicles

	RAMP ONE		RAIL	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance .	B177 A 7BX X 315 000102 08 16 22
	CE07				
	RAMP TWO	ITEM #:	16-E103 O/T 2	<div></div> FORD CREDIT	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.				

1FC3E4KK9PDD04385

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

rates may apply.
Text HELP
for help

www.ford.com/help/privacy-terms/