



Go Further

ford.com

VEHICLE DESCRIPTION

E-SERIES

2022 E-450 STRIPPED DRW
DRW 158" WHEELBASE
7.3L V8 PREMIUM-RATED ENG.
ELEC 6-SPD AOD W/TOW-HAUL

EXTERIOR

INTERIOR
LESS TRIM

ND C32228

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- AUXILIARY FUEL PORT
- LT225/75R16E BSW TIRES
- WIPERS- INTERMITTENT

INTERIOR

- STEERING - TILT/TELESCOPIC

FUNCTIONAL

- BATTERY - 78 AMP-HR
- FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL
- TRACTION CONTROL

WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

BUILT

TOUGH

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

4005-096N01/01/21 LF030Y
PREFERRED EQUIPMENT PKG.790A
7.3L V8 PREMIUM-RATED ENG.
.456 RATIO REGULAR AXLE X83
14500# GVWR PACKAGE
SHIP-THRU NATIONAL FLEET SERV
50 STATE EMISSIONS
CRUISE CONTROL
AIR CONDITIONING, PREP
FRONT MAX GAWR

(MSRP)

NO CHARGE

NO CHARGE

NO CHARGE

240.00

400.00

NO CHARGE

PRICE INFORMATION

BASE PRICE

\$32,660.00

TOTAL OPTIONS/OTHER

640.00

TOTAL VEHICLE & OPTIONS/OTHER

33,300.00

DESTINATION & DELIVERY

1,295.00

(MSRP)

	RAMP ONE		CONVOY	ITEM #:	21-M089 O/T 5C	FORD CREDIT	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance .
	CY07						
	RAMP TWO						
	CE07						
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.					SPECIAL ORDER	
						MK081 N RB 2X 215 000808 10 08 21	

EPA DOT

Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

fueleconomy.gov

Calculate personalized estimates and compare vehicles





Go Further



WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

rates may apply. Text HELP for help



www.ford.com/help/privacy-terms/