

ford.com

## E-SERIES

2022 E-450 STRIPPED DRW DRW 158" WHEELBASE 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL** 

## ND C28222

**INTERIOR LESS TRIM** 

#### STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

#### **EXTERIOR**

- AUXILIARY FUEL PORT
- LT225/75R16E BSW TIRES
- WIPERS- INTERMITTENT

#### <u>INTERIOR</u>

• STEERING - TILT/TELESCOPIC

### **FUNCTIONAL**

- BATTERY 78 AMP-HR • FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

#### SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL
- TRACTION CONTROL

#### WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

#### **INCLUDED ON THIS VEHICLE**

#### **OPTIONAL EQUIPMENT/OTHER**

4005-096N01/01/21 LF030Y PREFERRED EQUIPMENT PKG.790A 7.3L V8 PREMIUM-RATED ENG. .4.56 RATIO REGULAR AXLE X83 14500# GVWR PACKAGE SHIP-THRU NATIONAL FLEET SERV **50 STATE EMISSIONS** CRUISE CONTROL AIR CONDITIONING, PREP

FRONT MAX GAWR

**NO CHARGE NO CHARGE** NO CHARGE **NO CHARGE** 240.00

400.00

**NO CHARGE** 

### (MSRP)

BASE PRICE TOTAL OPTIONS/OTHER

#### (MSRP) **PRICE INFORMATION** \$32,660.00

**TOTAL VEHICLE & OPTIONS/OTHER** 

640.00

33,300.00 1,295.00

## EPA Fuel Economy and Environment

## **FUEL ECONOMY RATINGS NOT** REQUIRED ON THIS VEHICLE

### fueleconomy.gov Calculate personalized estimates and compare vehicles









## **CY07**

RAMP TWO

CONVOY

21-M032 O/T 5C **CE07** 

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

### TOTAL MSRP

\$34,595.00



Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

### **SPECIAL ORDER**

MK011 N RB 2X 215 000044 10 01 21

# 1FC4E4KN1NDC28222

warning: Operating, servicing and maintaining a passenger vehicle, process, servicing to cause cancer and birth defects or other reports. lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



