ford.com

E-SERIES

2022 E-450 STRIPPED DRW DRW 158" WHEELBASE 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL**

ND C30957

INTERIOR LESS TRIM

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- AUXILIARY FUEL PORT
- LT225/75R16E BSW TIRES
- WIPERS- INTERMITTENT

<u>INTERIOR</u>

• STEERING - TILT/TELESCOPIC

- **FUNCTIONAL**
 - BATTERY 78 AMP-HR • FLEET TELEMATICS MODEM
 - HILL START ASSIST
 - TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL TRACTION CONTROL

WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER 4005-096N01/01/21 LF030Y PREFERRED EQUIPMENT PKG.790A 7.3L V8 PREMIUM-RATED ENG. .4.56 RATIO REGULAR AXLE X83 14500# GVWR PACKAGE SHIP-THRU NATIONAL FLEET SERV **50 STATE EMISSIONS** CRUISE CONTROL AIR CONDITIONING, PREP

FRONT MAX GAWR

NO CHARGE NO CHARGE NO CHARGE **NO CHARGE**

240.00

400.00

NO CHARGE

TOTAL OPTIONS/OTHER

TOTAL VEHICLE & OPTIONS/OTHER

(MSRP)

PRICE INFORMATION BASE PRICE

(MSRP)

\$32,660.00 640.00

33,300.00 1,295.00

EPA Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

fueleconomy.gov Calculate personalized estimates and compare vehicles









CY07

RAMP TWO

CE07

21-M064 O/T 5C

This label is affixed pursuant to the Federal Automobile

Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed

options or accessories are not included unless listed above.

CONVOY

FORD CREDIT

Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

\$34,595.00

SPECIAL ORDER

TOTAL MSRP

MK041 N RB 2X 215 000639 10 04 21

1FC4E4KN3NDC30957

warning: Operating, servicing and maintaining a passenger vehicle, process, servicing to cause cancer and birth defects or other reports. lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



