# **E-SERIES**

2022 E-450 STRIPPED DRW DRW 158" WHEELBASE 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL** 

## ND C32239

**INTERIOR LESS TRIM** 

### ford.com

## STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

### **EXTERIOR**

- AUXILIARY FUEL PORT
- LT225/75R16E BSW TIRES
- WIPERS- INTERMITTENT

## <u>INTERIOR</u>

• STEERING - TILT/TELESCOPIC

### **FUNCTIONAL**

- BATTERY 78 AMP-HR • FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

### SAFETY/SECURITY

- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- ELECTRONIC STABILITY CNTRL
- TRACTION CONTROL

### WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

### **INCLUDED ON THIS VEHICLE**

OPTIONAL EQUIPMENT/OTHER 4005-096N01/01/21 LF030Y PREFERRED EQUIPMENT PKG.790A 7.3L V8 PREMIUM-RATED ENG. .4.56 RATIO REGULAR AXLE X83 14500# GVWR PACKAGE SHIP-THRU NATIONAL FLEET SERV **50 STATE EMISSIONS** 

CRUISE CONTROL AIR CONDITIONING, PREP FRONT MAX GAWR

### (MSRP)

**NO CHARGE** NO CHARGE **NO CHARGE** 

**CY07** 

**CE07** 

RAMP TWO

### **NO CHARGE**

240.00 400.00 **NO CHARGE** 

**PRICE INFORMATION** BASE PRICE

TOTAL OPTIONS/OTHER

**TOTAL VEHICLE & OPTIONS/OTHER** 1,295.00

## (MSRP)

\$32,660.00 640.00

33,300.00

# EPA Fuel Economy and Environment

# **FUEL ECONOMY RATINGS NOT** REQUIRED ON THIS VEHICLE

## fueleconomy.gov Calculate personalized estimates and compare vehicles









## \$34,595.00

TOTAL MSRP

21-M100 O/T 5C

CONVOY

This label is affixed pursuant to the Federal Automobile

Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed

options or accessories are not included unless listed above.

FORD CREDIT

Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

## **SPECIAL ORDER**

MK061 N RB 2X 215 000799 10 06 21

# 1FC4E4KN5NDC32239

warning: Operating, servicing and maintaining a passenger vehicle, process, servicing to cause cancer and birth defects or other reports. lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



